Photo's LID565/LID575 MID Range series:

Colours of housing might differ from original colour. Pictures are taken from first samples.
Difference LID565/LID575 is the firmware (representation of the code). The hardware is identical.

Picture 1 Front view LID565/575 MID RANGE.

Picture 2 Inside view LID565/575

FCC ID TLH8471301

Location of serial number & part number. Inside of battery compartment

Picture 3 Backside of LID565/575 (without battery door)

An example of the label is given below:

LID565-AKC
Firmware: V1.00
FCC ID TLH8471301
SN 3208001

LID575
Firmware : V1.00
FCC ID TLH8471301
SN 3208001