Specification Information

Specification Name : Quick Guide
Package : Sensor Pad box
Size : 210mm x 148mm; 4 pages
Method : Double side printing

Black 100%
C 0 M 0 Y 0 K 100

Grey 100%
C 0 M 0 Y 0 K 70

White 100%
C 0 M 0 Y 0 K 0

297mm

210mm

Cybertecture® Mirror
Reflective window into a digital life

Specification

- Weight capacity : 150 kg or 330 lb
- Weight graduation : 100g or 0.2 lb
- 2.4GHz wireless connection
- Maximum distance between Sensor Pad and Cybertecture® Mirror for correct functioning: 5 meters or 15 feet (open environment)
- Low battery indicator
- Sensor Pad powered by 1 piece 9V alkaline battery type 6LR61 or equivalent (not included)

Maintenance

- Do not disassemble the unit. Incorrect handling may cause injury or damage to the product.
- Remove the battery from its compartment when device is not used for an extended period.
- Use a dampened cloth to clean the product after use. Do not use detergent or immerse the unit in water.
- Avoid excessive impact or vibration to the unit, such as dropping the product onto the floor.

Precaution of Use

- This product is not suitable for persons with implanted electronic medical equipment, such as a pacemaker. The low-level electrical signal that passes through the body may cause malfunction of the medical equipment. When in doubt, please consult your physician.
- For pregnant women, professional athletes, bodybuilders and people who have body implants such as artificial limbs, contraceptive devices, metal plates or screws, the results given by the device may be inaccurate. The reason is that fat is not as evenly distributed around the body as it would be at other times thus causing inaccurate results. However there is no health risk associated with using the device.
- The product is not intended for professional usage in hospitals or medical facilities; it is intended for home/consumer use only.

Sensor Pad
Quick Guide

copyright © 2010 James Law Cybertecture (Mirror) Ltd.
All Rights Reserved.
www.cybertecturemirror.com

JAMES LAW
CYBERTECTURE®

Identification of Parts

LCD Display

Sync Button   Battery Compartment

ITO Electrode X 4

Load Cell X 4

Front

Back

LCD Display

OVERLOAD ERROR
Cybertecture®
mirror
LOADING . . .

1 **Overload**
Sensor Pad load is over the limit, please step off the device immediately!

2 **Error**
Measurement cannot be taken, please try again

3 **Low Battery**
Battery is low, please replace the battery

4 **Cybertecture® Mirror logo**
Measurement completed, data will be displayed on the Cybertecture® Mirror

5 **Loading**
Measurement is in progress, please stand still on the Sensor Pad

Initialization

1. Insert battery in the battery compartment.

2. Press the sync button on the back of the Sensor Pad and the respective button on the Cybertecture® Mirror (For details on how to operate Cybertecture® Mirror refer to the Cybertecture® Mirror User Manual).

3. Tap the Sensor Pad once. "LOADING" icon will turn on. *DO NOT* step on the Sensor Pad until the "LOADING" icon is turned off.

Sync Button

Operation

- To get accurate reading, place the Sensor Pad on a hard and flat surface. Stand still on the Sensor Pad until the "Cybertecture® Mirror" logo comes up.

- Stand with your bare feet on the platform in a way that will provide maximum contact with Sensor Pad platform. This ensures the best contact between your feet and the electrodes.

Help Line

Email :   support@cybertecturemirror.com
Tel :   (852) 3925 9036
Address :   402 - 3 Innocentre, 72 Tat Chee Ave,
Kowloon Tong, Kowloon,
Hong Kong SAR