



Internal photographs of equipment under test
Inside enclosure



Back Side




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

FireBoard Labs LLC
HVIN: FBXIR21 PMN: Spark
Test: 211004
Test to: CFR47 15C, RSS-247
File: FBXIR21 IntPho


SN's: FCC1 / FCC2
FCC ID: 2A29A-FBXIR21
IC: 27842-FBXIR21
Date: November 18, 2021
Page 1 of 3

Front side display removed



2400 MHz antenna

Back Side Display removed




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1


FireBoard Labs LLC
HVIN: FBXIR21 PMN: Spark
Test: 211004
Test to: CFR47 15C, RSS-247
File: FBXIR21 IntPho

SN's: FCC1 / FCC2
FCC ID: 2A29A-FBXIR21
IC: 27842-FBXIR21
Date: November 18, 2021
Page 2 of 3

USB-C and NFC antenna Daughter board



NFC Coil Antenna



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

FireBoard Labs LLC
HVIN: FBXIR21 PMN: Spark
Test: 211004
Test to: CFR47 15C, RSS-247
File: FBXIR21 IntPho

SN's: FCC1 / FCC2
FCC ID: 2A29A-FBXIR21
IC: 27842-FBXIR21
Date: November 18, 2021
Page 3 of 3