

CC STC 00299429 2024 TR

Amazon.com Services LLC

410 Terry Avenue, Seattle Washington 98109, United States

Tel: 1-650-426-1100

Date: August 9, 2024

FCC Laboratory
7435 Oakland Mills Rd
Columbia MD 21046

To whom it may concern,

Re: Change of Identification for FCC ID: 2A4DH-6387

We hereby request a change in identification as specified under 47 CFR §2.933 of the FCC rules. This change applies to the 2A4DH-6387 Digital Media Receiver, originally granted on 09/01/2023 with FCC ID: 2A4DH-6387. Amazon.com Services LLC intends to market the above referenced product under new FCC ID: 2A4DH-8592. The product bearing the new FCC ID is electrically identical to the originally certified equipment. The original test results continue to be representative of and applicable to the equipment bearing the changed identification.

Sincerely yours,

Signed by:


Amit Gaikwad

C482B8B5954F451

Amit Gaikwad

device-certification@amazon.com

