


Appendix C. #Antenna Locatin & DistanceFront view

KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR22-SPF0022
Page (54) of (58)




Appendix D. EUT Photo

D.1) Front



D.2) Rear



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR22-SPF0022
Page (55) of (58)

**D.3) Left****D.4) Right**

KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR22-SPF0022
Page (56) of (58)


**D.5) Top****D.6) Bottom**

Appendix E. Test Setup Photo

E.1) Body_Front (0 mm)




E.2) Body_Rear(0 mm)



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR22-SPF0022
Page (58) of (58)

**E.3) Body_Left(0 mm)****End of test report**

This test report shall not be reproduced, except in full, without the written approval
KCTL-TIA002-004/5

KP22-00638