

Shenzhen Langsheng Hengchi Trading Co., LTD

Nov 30, 2022

Subject: Tuning and Adjustment of signal booster, FCC ID: 2A9A8-FB20221001

There are no external tuning adjustments, the amplifier is factory set not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Yours sincerely,

Heng Zhang


Signature: