

Tune-up Procedure

Each unit is tested during unit production for functionality using a pass/fail criterion. The unit is then given pass/fail status based on the measured parameters. The pass/fail threshold is determined by engineering during product development. Compliant samples continue through production and non-compliant units are removed. No tuning of software parameters or hardware is required.