



External Photos of the EUT

BDE-MB1354P101UU32:



Fig. 1



Fig. 2






Fig. 3

BDE-MB1354P101NN32:



Fig. 4





Fig. 5



Fig. 6






Fig. 7

BDE-MB1354P101UA32:



Fig. 8






Fig. 9




Fig. 10





BDE-MB1354P101NA32:



Fig. 11




Fig. 12





Fig. 13

BDE-MB1352P1NA32:



Fig. 14





Fig. 15



Fig. 16





BDE-MB1352P1NN32:



Fig. 17




Fig. 18






Fig. 19

BDE-MB1352P1NU32:



Fig. 20





Fig. 21




Fig. 22





BDE-MB1352P1UA32:




Fig. 23




Fig. 24






Fig. 25

BDE-MB1352P1UN32:



Fig. 26





Fig. 27




Fig. 28





BDE-MB1352P1UU32:



Fig. 29



Fig. 30






Fig. 31

BDE-MB1352P71NA32:



Fig. 32






Fig. 33




Fig. 34





BDE-MB1352P71NN32:



Fig. 35




Fig. 36






Fig. 37

BDE-MB1352P71NU32:



Fig. 38





Fig. 39




Fig. 40





BDE-MB1352P71UA32:




Fig. 41



Fig. 42






Fig. 43

BDE-MB1352P71UN32:



Fig. 44





Fig. 45




Fig. 46





BDE-MB1352P71UU32:



Fig. 47



Fig. 48






Fig. 49

BDE-MB1354P101NU32:



Fig. 50






Fig. 51




Fig. 52





BDE-MB1354P101UN32:



Fig. 53



Fig. 54






Fig. 55




Fig. 56






Fig. 57

