







2A-13A / 20+10MHz / QPSK / Mid+Low CH /
1@0-1@49




2A-13A / 20+10MHz / QPSK / Mid+Low CH /
1@99-1@0




2A-13A / 20+10MHz / QPSK / Mid+Low CH /
100@0-50@0









2A-13A / 20+10MHz / QPSK / Mid+Mid CH /
1@0-1@49









2A-13A / 20+10MHz / QPSK / Mid+Mid CH /
1@99-1@0




2A-13A / 20+10MHz / QPSK / Mid+Mid CH /
100@0-50@0

2A-13A / 20+10MHz / QPSK / Mid+High CH /
1@0-1@492A-13A / 20+10MHz / QPSK / Mid+High CH /
1@99-1@02A-13A / 20+10MHz / QPSK / Mid+High CH /
100@0-50@02A-13A / 20+10MHz / QPSK / High+Low CH /
1@0-1@492A-13A / 20+10MHz / QPSK / High+Low CH /
1@99-1@02A-13A / 20+10MHz / QPSK / High+Low CH /
100@0-50@0


2A-13A / 20+10MHz / QPSK / High+Mid CH /
1@0-1@492A-13A / 20+10MHz / QPSK / High+Mid CH /
1@99-1@02A-13A / 20+10MHz / QPSK / High+Mid CH /
100@0-50@02A-13A / 20+10MHz / QPSK / High+High CH /
1@0-1@492A-13A / 20+10MHz / QPSK / High+High CH /
1@99-1@02A-13A / 20+10MHz / QPSK / High+High CH /
100@0-50@0




REPORT No.: SZ24070315W11




2A-66A / 20+20MHz / QPSK / Low+Low CH /
1@0-1@99




2A-66A / 20+20MHz / QPSK / Low+Low CH /
1@99-1@0




2A-66A / 20+20MHz / QPSK / Low+Low CH /
100@0-100@0



2A-66A / 20+20MHz / QPSK / Low+Mid CH /
1@0-1@99



2A-66A / 20+20MHz / QPSK / Low+Mid CH /
1@99-1@0



2A-66A / 20+20MHz / QPSK / Low+Mid CH /
100@0-100@0









Shenzhen Morlab Communications Technology Co., Ltd.
FL.1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China


Tel: 86-755-36698555

Http://www.morlab.cn


Fax: 86-755-36698525

E-mail: service@morlab.cn


2A-66A / 20+20MHz / QPSK / Low+High CH /
1@0-1@992A-66A / 20+20MHz / QPSK / Low+High CH /
1@99-1@02A-66A / 20+20MHz / QPSK / Low+High CH /
100@0-100@02A-66A / 20+20MHz / QPSK / Mid+Low CH /
1@0-1@992A-66A / 20+20MHz / QPSK / Mid+Low CH /
1@99-1@02A-66A / 20+20MHz / QPSK / Mid+Low CH /
100@0-100@0




2A-66A / 20+20MHz / QPSK / Mid+Mid CH /
1@0-1@99




2A-66A / 20+20MHz / QPSK / Mid+Mid CH /
1@99-1@0




2A-66A / 20+20MHz / QPSK / Mid+Mid CH /
100@0-100@0



2A-66A / 20+20MHz / QPSK / Mid+High CH /
1@0-1@99



2A-66A / 20+20MHz / QPSK / Mid+High CH /
1@99-1@0



2A-66A / 20+20MHz / QPSK / Mid+High CH /
100@0-100@0