

US Tech Test Report:

FCC ID:

Test Report Number:

Issue Date:

Customer:

Model:

FCC Part 15 Certification

2AD9R-CO1301

15-0021

February 13, 2015

Controlant EHF

CO 13.01

EXTERNAL PHOTOGRAPHS



Figure 1. Top of EUT with Case

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AD9R-CO1301
15-0021
February 13, 2015
Controlant EHF
CO 13.01




Figure 2. Bottom of EUT with Case

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AD9R-CO1301
15-0021
February 13, 2015
Controlant EHF
CO 13.01



Figure 3. SMA Reverse Sex Connector

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AD9R-CO1301
15-0021
February 13, 2015
Controlant EHF
CO 13.01



Figure 4. Q8019-900LW Antenna

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AD9R-CO1301
15-0021
February 13, 2015
Controlant EHF
CO 13.01



Figure 5. Q868-A AP Antenna