

**ANNEX 2 TO TEST REPORT # EMCC-040197.1G, 2021-02-02****EXTERNAL PHOTOGRAPHS OF EQUIPMENT UNDER TEST****EQUIPMENT UNDER TEST:**

|                         |                                                |
|-------------------------|------------------------------------------------|
| Trade Name:             | Torque meter T40CB                             |
| Type, Serial Number(s): | T40CB S2, Rotor: 23444018, Stator: 233670005   |
| Application:            | Low Power Transceiver                          |
| FCC ID:                 | 2ADAT-T40S2TOS6                                |
| ISED IC:                | 12438A-T40S2TOS6                               |
| Manufacturer:           | Hottinger Brüel & Kjaer GmbH                   |
| Address:                | Im Tiefen See 45<br>64293 Darmstadt<br>Germany |
| Phone:                  | +49 6151 803 8790                              |
| E-Mail:                 | Gesa.Biegling@hbkworld.com                     |

**RELEVANT STANDARD(S) :** 47 CFR § 15.203, § 15.207, § 15.209  
RSS-Gen Issue 5, RSS-210 Issue 10 Amendment 1, RSS-102 Issue 5

**MEASUREMENT PROCEDURE:**☒ ANSI C63.10-2013☒ SPR-002 Issue 1**ILLUSTRATION LIST ANNEX 2**


|                                                           |   |
|-----------------------------------------------------------|---|
| Photograph A2-1: EUT on wooden support, front side        | 2 |
| Photograph A2-2: EUT on wooden support, righthand side    | 2 |
| Photograph A2-3: EUT on wooden support, back side         | 3 |
| Photograph A2-4: EUT on wooden support, lefthand side     | 3 |
| Photograph A2-5: Detailed view stator unit, lefthand side | 4 |
| Photograph A2-6: Detail on serial number on rotor         | 4 |
| Photograph A2-7: Detail on serial number on stator        | 5 |

Test on Hottinger Brüel & Kjaer GmbH T40CB S2 to 47 CFR § 15.203, § 15.207, § 15.209 and  
RSS-Gen Issue 5, RSS-210 Issue 10 Amendment 1, RSS-102 Issue 5

---



**Photograph A2-1: EUT on wooden support, front side**



**Photograph A2-2: EUT on wooden support, righthand side**

Test on Hottinger Brüel & Kjaer GmbH T40CB S2 to 47 CFR § 15.203, § 15.207, § 15.209 and  
RSS-Gen Issue 5, RSS-210 Issue 10 Amendment 1, RSS-102 Issue 5

---




**Photograph A2-3: EUT on wooden support, back side**



**Photograph A2-4: EUT on wooden support, lefthand side**

Test on Hottinger Brüel & Kjaer GmbH T40CB S2 to 47 CFR § 15.203, § 15.207, § 15.209 and  
RSS-Gen Issue 5, RSS-210 Issue 10 Amendment 1, RSS-102 Issue 5

---



**Photograph A2-5: Detailed view stator unit, left hand side**



**Photograph A2-6: Detail on serial number on rotor**

Test on Hottinger Brüel & Kjaer GmbH T40CB S2 to 47 CFR § 15.203, § 15.207, § 15.209 and  
RSS-Gen Issue 5, RSS-210 Issue 10 Amendment 1, RSS-102 Issue 5

---



**Photograph A2-7: Detail on serial number on stator**