

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification 15.247
2ADWTCCS01
20-0359
January 29, 2021
Southern States LLC.
Cap Can Sensor

EXTERNAL PHOTOGRAPHS



Figure 1. Top of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification 15.247
2ADWTCCS01
20-0359
January 29, 2021
Southern States LLC.
Cap Can Sensor



Figure 2. Bottom of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification 15.247
2ADWTCCS01
20-0359
January 29, 2021
Southern States LLC.
Cap Can Sensor



Figure 3. Left Side of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification 15.247
2ADWTCCS01
20-0359
January 29, 2021
Southern States LLC.
Cap Can Sensor



Figure 4. Right Side of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification 15.247
2ADWTCCS01
20-0359
January 29, 2021
Southern States LLC.
Cap Can Sensor




Figure 5. Front of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification 15.247
2ADWTCCS01
20-0359
January 29, 2021
Southern States LLC.
Cap Can Sensor




Figure 6. Back of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification 15.247
2ADWTCCS01
20-0359
January 29, 2021
Southern States LLC.
Cap Can Sensor



Figure 7. Label Location