

FCC ID: 2ADYY-BD4A

The device was retested about RF conducted test data for this report (Report No.: SZNS211209-63796E-RF-00A-M3). The brief updated contents are as follows:

1. Updated the report number for whole report.
2. Updated prepared and approved signature at Page 1.
3. Updated the test date at Page 1 and report date at Page 1&4.
4. Updated the maximum conducted power at Page 5.
5. Updated the uncertainties associated for RF conducted test and Test Facility at Page 6.
6. Added the notes under the summary table at Page 9.
7. Updated the test equipment list for RF conducted test at Page 11.
8. Updated the setup block and environmental conditions for Page 25-31.
9. Updated the RF test data and plots for each item for Page 32-72.
10. Form 731, update the power level information according to new test.