



Please refer to following plots:




Date: 21.FEB.2022 17:30:37




Date: 21.FEB.2022 17:30:48

Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:31:05

Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:31:17

Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:31:37

Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:31:49

Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:32:10

Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:32:22

Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:32:39

Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:32:51

Band 2\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:33:08

Band 2\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:33:20

Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:33:38

Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:33:50

Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:34:11

Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:34:22

Band 2\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:34:43

Band 2\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:34:54

Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:35:18

Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:35:30

Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:35:52

Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:36:04

Band 2\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:36:24

Band 2\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:36:35

Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:37:00

Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:37:12

Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:37:36

Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:37:47

Band 2\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:38:15

Band 2\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:38:26

Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:38:51

Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:39:03

Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:39:27

Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:39:38

Band 2\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:40:05

Band 2\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:40:17

Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:40:35

Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:40:47

Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:41:07

Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:41:19

Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:41:36

Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:41:48

Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:42:07

Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:42:18

Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:42:36

Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:42:47

Band 4\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:43:04

Band 4\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:43:16

Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:43:34

Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:43:46

Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:44:06

Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:44:18

Band 4\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:44:39

Band 4\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:44:53

Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:45:14

Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:45:25

Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:45:48

Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:46:00

Band 4\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:46:22

Band 4\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:46:34

Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:46:59

Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:47:10

Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:47:38

Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:47:49

Band 4\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:48:13

Band 4\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:48:25

Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:48:50

Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:49:01

Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:49:25

Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:49:37

Band 4\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:50:04

Band 4\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 17:50:15

Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:50:38

Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 21.FEB.2022 17:50:49

Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:51:10

Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 21.FEB.2022 17:51:21

Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:51:42

Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 21.FEB.2022 17:51:53

Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:52:12

Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 21.FEB.2022 17:52:24

Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:52:44

Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 21.FEB.2022 17:52:59

Band 5\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:53:19

Band 5\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 21.FEB.2022 17:53:31

Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:53:49

Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 21.FEB.2022 17:54:01

Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:54:18

Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 21.FEB.2022 17:54:30

Band 5\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:54:50

Band 5\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 21.FEB.2022 17:55:02

Band 5\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:55:26

Band 5\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 21.FEB.2022 17:55:37

Band 5\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:56:00

Band 5\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 21.FEB.2022 17:56:12

Band 5\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:56:31

Band 5\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 21.FEB.2022 17:56:43

Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:57:04

Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 21.FEB.2022 17:57:16

Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:57:33

Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 21.FEB.2022 17:57:45

Band 7\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:58:02

Band 7\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 21.FEB.2022 17:58:14

Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:58:34

Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 21.FEB.2022 17:58:46

Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:59:09

Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 21.FEB.2022 17:59:20

Band 7\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 17:59:40

Band 7\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 21.FEB.2022 17:59:51

Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:00:17

Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 21.FEB.2022 18:00:28

Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:00:52

Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 21.FEB.2022 18:01:04

Band 7\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:01:28

Band 7\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 21.FEB.2022 18:01:39

Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:02:04

Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 21.FEB.2022 18:02:16

Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:02:40

Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 21.FEB.2022 18:02:52

Band 7\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:03:16

Band 7\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 21.FEB.2022 18:03:27

Band 17\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:03:49

Band 17\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 21.FEB.2022 18:04:00

Band 17\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:04:18

Band 17\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 21.FEB.2022 18:04:29

Band 17\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:04:50

Band 17\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 21.FEB.2022 18:05:01

Band 17\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:05:22

Band 17\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 21.FEB.2022 18:05:33

Band 17\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:05:56

Band 17\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 21.FEB.2022 18:06:08

Band 17\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:06:27

Band 17\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 21.FEB.2022 18:06:39

### Band 38\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 09:44:44

### Band 38\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 09:44:55

Band 38\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 09:45:13

Band 38\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 09:45:24

Band 38\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 09:45:45

Band 38\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 09:45:56

Band 38\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 09:46:17

Band 38\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 09:46:29

Band 38\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 09:46:48

Band 38\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 09:47:00

Band 38\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 09:47:23

Band 38\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 09:47:34

Band 38\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 09:48:02

Band 38\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 09:48:14

Band 38\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 09:48:38

Band 38\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 09:48:50

Band 38\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 09:49:17

Band 38\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 09:49:28

Band 38\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 09:49:54

Band 38\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 09:50:06

Band 38\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 09:50:33

Band 38\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 09:50:44

Band 38\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 09:51:12

Band 38\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 09:51:23

### Band 41\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 12:32:12

### Band 41\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 12:32:23

Band 41\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 12:32:44

Band 41\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 12:32:55

Band 41\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 12:33:13

Band 41\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 12:33:25

Band 41\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 12:33:48

Band 41\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 12:34:00

Band 41\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 12:34:20

Band 41\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 12:34:31

Band 41\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 12:34:51

Band 41\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 12:35:02

Band 41\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 12:35:27

Band 41\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 12:35:39

Band 41\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 12:36:03

Band 41\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 12:36:14

Band 41\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 12:36:38

Band 41\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 12:36:50

Band 41\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 12:37:18

Band 41\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 12:37:30

Band 41\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 12:37:57

Band 41\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 12:38:08

Band 41\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 22.FEB.2022 12:38:32

Band 41\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 22.FEB.2022 12:38:44

### Band 66\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:07:01

### Band 66\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 18:07:12

Band 66\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:07:30

Band 66\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 18:07:41

Band 66\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:08:02

Band 66\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 18:08:13

Band 66\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:08:35

Band 66\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 18:08:46

Band 66\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:09:07

Band 66\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 18:09:18

Band 66\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:09:36

Band 66\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 18:09:47

Band 66\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:10:06

Band 66\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 18:10:17

Band 66\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:10:38

Band 66\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 18:10:49

Band 66\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:11:07

Band 66\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 18:11:18

Band 66\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:11:39

Band 66\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 18:11:50

Band 66\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:12:13

Band 66\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 18:12:25

Band 66\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:12:44

Band 66\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 18:12:56

Band 66\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:13:24

Band 66\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 18:13:35

Band 66\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:14:03

Band 66\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 18:14:14

Band 66\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:14:38

Band 66\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 18:14:50

Band 66\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:15:18

Band 66\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 18:15:29

Band 66\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 21.FEB.2022 18:15:56

Band 66\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 21.FEB.2022 18:16:08

Band 66\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 21.FEB.2022 18:16:35

Band 66\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)



Date: 21.FEB.2022 18:16:47