



n77_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB180@0 -40.26dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:02:27

n77_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -44.40dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:09:44

n77_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@188 -44.22dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:01:45

n77_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB180@0 -46.15dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:22:08

n77_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB1@0 -47.47dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:20:38

n77_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB1@188 -46.48dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:21:24

n77_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB1@0 -43.23dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:23:02

n77_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB1@216 -45.11dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:23:47

n77_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB216@0 -47.03dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:24:33

n77_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -45.03dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:25:23

n77_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@216 -45.24dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:26:13

n77_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB216@0 -48.31dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:26:58

n77_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB1@0 -48.15dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:27:48

n77_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB1@216 -41.47dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 12:31:31

n77_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB216@0 -47.69dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:29:18

n77_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB1@0 -44.48dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:30:11

n77_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB1@244 -40.15dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:30:56

n77_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB243@0 -43.51dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:31:41

n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -48.45dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:32:31

n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@244 -46.68dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:33:16

n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB243@0 -48.32dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:34:03

n77_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB1@0 -45.93dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:34:59

n77_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB1@244 -41.32dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 12:32:27

n77_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB243@0 -47.15dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:36:29

n77_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB1@0 -46.99dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:37:21

n77_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB1@272 -47.97dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:38:07

n77_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB270@0 -45.15dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:38:53

n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -40.64dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 12:33:23

n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@272 -47.66dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:40:29

n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB270@0 -47.71dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaester Liang
Date: 15.AUG.2024 11:41:14

n77_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB1@0 -41.21dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:42:04

n77_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB1@272 -43.96dBm



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:42:51


n77_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB270@0 -47.91dBm



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:43:37


n78_2

n78_2_10MHz_30kHz_3555MHz_DFT-s-OFDM
QPSK_RB1@0 -47.93dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:20:07

n78_2_10MHz_30kHz_3555MHz_DFT-s-OFDM
QPSK_RB1@23 -47.74dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:21:00

n78_2_10MHz_30kHz_3555MHz_DFT-s-OFDM
QPSK_RB24@0 -47.74dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:21:53

n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -41.33dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:22:50

n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@23 -43.31dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:23:43

n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB24@0 -47.85dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:24:36

n78_2_10MHz_30kHz_3695MHz_DFT-s-OFDM
QPSK_RB1@0 -47.71dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:25:34

n78_2_10MHz_30kHz_3695MHz_DFT-s-OFDM
QPSK_RB1@23 -48.53dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:26:30

n78_2_10MHz_30kHz_3695MHz_DFT-s-OFDM
QPSK_RB24@0 -43.96dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:27:24

n78_2_15MHz_30kHz_3557.5MHz_DFT-s-OFDM
QPSK_RB1@0 -46.11dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:28:26

n78_2_15MHz_30kHz_3557.5MHz_DFT-s-OFDM
QPSK_RB1@37 -46.55dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:29:20

n78_2_15MHz_30kHz_3557.5MHz_DFT-s-OFDM
QPSK_RB36@0 -45.33dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:30:13

n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -46.37dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:31:10

n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@37 -47.12dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:32:04

n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB36@0 -45dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:32:58

n78_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM
QPSK_RB1@0 -46.42dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 15:33:56

n78_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM
QPSK_RB1@37 -40.07dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 15:34:49

n78_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM
QPSK_RB36@0 -48.29dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 15:35:43

n78_2_20MHz_30kHz_3560MHz_DFT-s-OFDM
QPSK_RB1@0 -47.82dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 15:48:14

n78_2_20MHz_30kHz_3560MHz_DFT-s-OFDM
QPSK_RB1@50 -44.85dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 15:49:09

n78_2_20MHz_30kHz_3560MHz_DFT-s-OFDM
QPSK_RB50@0 -43.57dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 15:50:04

n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -45.54dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:51:03

n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@50 -48.11dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:51:58

n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB50@0 -47.97dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:52:52

n78_2_20MHz_30kHz_3690MHz_DFT-s-OFDM
QPSK_RB1@0 -47.61dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:53:52

n78_2_20MHz_30kHz_3690MHz_DFT-s-OFDM
QPSK_RB1@50 -45.57dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:54:46

n78_2_20MHz_30kHz_3690MHz_DFT-s-OFDM
QPSK_RB50@0 -44.26dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:55:41

n78_2_30MHz_30kHz_3565MHz_DFT-s-OFDM
QPSK_RB1@0 -47.11dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:57:47

n78_2_30MHz_30kHz_3565MHz_DFT-s-OFDM
QPSK_RB1@77 -46.67dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:58:43

n78_2_30MHz_30kHz_3565MHz_DFT-s-OFDM
QPSK_RB75@0 -46.25dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:59:38

n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.61dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:00:38

n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@77 -48dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:01:33

n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB75@0 -47.86dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:02:27

n78_2_30MHz_30kHz_3685MHz_DFT-s-OFDM
QPSK_RB1@0 -48.20dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:03:28

n78_2_30MHz_30kHz_3685MHz_DFT-s-OFDM
QPSK_RB1@77 -48.14dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:04:25

n78_2_30MHz_30kHz_3685MHz_DFT-s-OFDM
QPSK_RB75@0 -44.58dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:05:19

n78_2_40MHz_30kHz_3570MHz_DFT-s-OFDM
QPSK_RB100@0 -46.69dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:08:13

n78_2_40MHz_30kHz_3570MHz_DFT-s-OFDM
QPSK_RB1@0 -47.55dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:06:22

n78_2_40MHz_30kHz_3570MHz_DFT-s-OFDM
QPSK_RB1@105 -43.80dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:07:19

n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB100@0 -47.65dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:11:04

n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.07dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:09:13

n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@105 -47.44dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:10:09

n78_2_40MHz_30kHz_3680MHz_DFT-s-OFDM
QPSK_RB100@0 -44.81dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:25:07

n78_2_40MHz_30kHz_3680MHz_DFT-s-OFDM
QPSK_RB1@0 -44.26dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:12:05

n78_2_40MHz_30kHz_3680MHz_DFT-s-OFDM
QPSK_RB1@105 -40.65dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:13:03

n78_2_50MHz_30kHz_3575MHz_DFT-s-OFDM
QPSK_RB128@0 -46.23dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:16:51

n78_2_50MHz_30kHz_3575MHz_DFT-s-OFDM
QPSK_RB1@0 -46.22dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:26:12

n78_2_50MHz_30kHz_3575MHz_DFT-s-OFDM
QPSK_RB1@132 -47.43dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:15:56

n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB128@0 -47.65dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:27:13

n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -40.68dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:17:57

n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@132 -43.05dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:18:55

n78_2_50MHz_30kHz_3675MHz_DFT-s-OFDM
QPSK_RB128@0 -48.03dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:34:18

n78_2_50MHz_30kHz_3675MHz_DFT-s-OFDM
QPSK_RB1@0 -44.97dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:32:25

n78_2_50MHz_30kHz_3675MHz_DFT-s-OFDM
QPSK_RB1@132 -47.58dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:33:23

n78_2_60MHz_30kHz_3580MHz_DFT-s-OFDM
QPSK_RB162@0 -47.64dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:37:14

n78_2_60MHz_30kHz_3580MHz_DFT-s-OFDM
QPSK_RB1@0 -45.54dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:35:22

n78_2_60MHz_30kHz_3580MHz_DFT-s-OFDM
QPSK_RB1@161 -47.35dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 11:54:04

n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB162@0 -42.63dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:40:08

n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -43.04dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:38:15

n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@161 -44.74dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 11:55:20

n78_2_60MHz_30kHz_3670MHz_DFT-s-OFDM
QPSK_RB162@0 -44.60dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:43:04

n78_2_60MHz_30kHz_3670MHz_DFT-s-OFDM
QPSK_RB1@0 -44.84dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 18:06:10

n78_2_60MHz_30kHz_3670MHz_DFT-s-OFDM
QPSK_RB1@161 -45.28dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 11:56:27


n78_2_70MHz_30kHz_3585MHz_DFT-s-OFDM
QPSK_RB180@0 -44.01dBm




n78_2_70MHz_30kHz_3585MHz_DFT-s-OFDM
QPSK_RB1@0 -42.49dBm




n78_2_70MHz_30kHz_3585MHz_DFT-s-OFDM
QPSK_RB1@188 -43.38dBm




n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB180@0 -46.47dBm




n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -40.18dBm



n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@188 -43.70dBm




n78_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB180@0 -46.15dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:52:12

n78_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB1@0 -44.98dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:50:17

n78_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB1@188 -45.29dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:51:15

n78_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB1@0 -44.54dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:53:18

n78_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB1@216 -45.19dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:54:17

n78_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB216@0 -43.99dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:55:15

n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -44.59dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 18:09:24

n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@216 -44.64dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 18:10:24

n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB216@0 -44.32dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 16:58:16

n78_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB1@0 -42.42dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 18:11:27

n78_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB1@216 -48.04dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 11:57:37

n78_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB216@0 -47.85dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 17:01:15

n78_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB1@0 -44.84dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 11:58:45

n78_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB1@244 -48.05dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 11:59:55

n78_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB243@0 -43.10dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 17:04:25

n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -45.93dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 12:01:11

n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@244 -40.46dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 17:07:02

n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB243@0 -45.57dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 18:16:38

n78_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB1@0 -43.53dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 17:09:02

n78_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB1@244 -48.30dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 12:02:21

n78_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB243@0 -46.06dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 17:10:57

n78_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB1@0 -42.91dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 18:18:48

n78_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB1@272 -47.63dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 13:05:40

n78_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB270@0 -48.24dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 18:20:45

n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -40.25dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 18:21:48

n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@272 -47.72dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 13:27:34

n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB270@0 -47.51dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 18:23:44

n78_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB1@0 -48.05dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 13:07:59

n78_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB1@272 -41.37dBm



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 13:09:06

n78_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB270@0 -47.71dBm



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 19:26:45