




n77\_2\_20MHz\_30kHz\_3625MHz\_DFT-s-OFDM 64  
QAM\_RB50@0 18.028MHz




n77\_2\_20MHz\_30kHz\_3625MHz\_DFT-s-OFDM 256  
QAM\_RB50@0 18.017MHz



n77\_2\_20MHz\_30kHz\_3625MHz\_CP-OFDM  
QPSK\_RB51@0 18.119MHz




n77\_2\_20MHz\_30kHz\_3625MHz\_CP-OFDM 16  
QAM\_RB51@0 18.188MHz




n77\_2\_20MHz\_30kHz\_3625MHz\_CP-OFDM 64  
QAM\_RB51@0 18.170MHz




n77\_2\_20MHz\_30kHz\_3625MHz\_CP-OFDM 256  
QAM\_RB51@0 18.186MHz



n77\_2\_20MHz\_30kHz\_3690MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB50@0 18.015MHz




n77\_2\_20MHz\_30kHz\_3690MHz\_DFT-s-OFDM  
QPSK\_RB50@0 18.026MHz



n77\_2\_20MHz\_30kHz\_3690MHz\_DFT-s-OFDM 16  
QAM\_RB50@0 18.027MHz




n77\_2\_20MHz\_30kHz\_3690MHz\_DFT-s-OFDM 64  
QAM\_RB50@0 18.027MHz



n77\_2\_20MHz\_30kHz\_3690MHz\_DFT-s-OFDM 256  
QAM\_RB50@0 18.084MHz




n77\_2\_20MHz\_30kHz\_3690MHz\_CP-OFDM  
QPSK\_RB51@0 18.242MHz




n77\_2\_20MHz\_30kHz\_3690MHz\_CP-OFDM 16  
QAM\_RB51@0 18.183MHz




n77\_2\_20MHz\_30kHz\_3690MHz\_CP-OFDM 64  
QAM\_RB51@0 18.180MHz




n77\_2\_20MHz\_30kHz\_3690MHz\_CP-OFDM 256  
QAM\_RB51@0 18.192MHz



n77\_2\_30MHz\_30kHz\_3565MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB75@0 27.607MHz



n77\_2\_30MHz\_30kHz\_3565MHz\_DFT-s-OFDM  
QPSK\_RB75@0 27.622MHz



n77\_2\_30MHz\_30kHz\_3565MHz\_DFT-s-OFDM 16  
QAM\_RB75@0 27.748MHz



n77\_2\_30MHz\_30kHz\_3565MHz\_DFT-s-OFDM 64  
QAM\_RB75@0 27.629MHz



n77\_2\_30MHz\_30kHz\_3565MHz\_DFT-s-OFDM 256  
QAM\_RB75@0 27.523MHz



n77\_2\_30MHz\_30kHz\_3565MHz\_CP-OFDM  
QPSK\_RB78@0 27.851MHz




n77\_2\_30MHz\_30kHz\_3565MHz\_CP-OFDM 16  
QAM\_RB78@0 27.773MHz



n77\_2\_30MHz\_30kHz\_3565MHz\_CP-OFDM 64  
QAM\_RB78@0 27.762MHz




n77\_2\_30MHz\_30kHz\_3565MHz\_CP-OFDM 256  
QAM\_RB78@0 27.769MHz




n77\_2\_30MHz\_30kHz\_3625MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB75@0 27.635MHz




n77\_2\_30MHz\_30kHz\_3625MHz\_DFT-s-OFDM  
QPSK\_RB75@0 27.608MHz



n77\_2\_30MHz\_30kHz\_3625MHz\_DFT-s-OFDM 16  
QAM\_RB75@0 27.748MHz




n77\_2\_30MHz\_30kHz\_3625MHz\_DFT-s-OFDM 64  
QAM\_RB75@0 27.733MHz



n77\_2\_30MHz\_30kHz\_3625MHz\_DFT-s-OFDM 256  
QAM\_RB75@0 27.520MHz



n77\_2\_30MHz\_30kHz\_3625MHz\_CP-OFDM  
QPSK\_RB78@0 27.855MHz



n77\_2\_30MHz\_30kHz\_3625MHz\_CP-OFDM 16  
QAM\_RB78@0 27.863MHz




n77\_2\_30MHz\_30kHz\_3625MHz\_CP-OFDM 64  
QAM\_RB78@0 27.772MHz



n77\_2\_30MHz\_30kHz\_3625MHz\_CP-OFDM 256  
QAM\_RB78@0 27.754MHz



n77\_2\_30MHz\_30kHz\_3685MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB75@0 27.621MHz



n77\_2\_30MHz\_30kHz\_3685MHz\_DFT-s-OFDM  
QPSK\_RB75@0 27.618MHz



n77\_2\_30MHz\_30kHz\_3685MHz\_DFT-s-OFDM 16  
QAM\_RB75@0 27.741MHz

