



n77\_2\_30MHz\_30kHz\_3685MHz\_DFT-s-OFDM 64  
QAM\_RB75@0 27.624MHz




n77\_2\_30MHz\_30kHz\_3685MHz\_DFT-s-OFDM 256  
QAM\_RB75@0 27.505MHz




n77\_2\_30MHz\_30kHz\_3685MHz\_CP-OFDM  
QPSK\_RB78@0 27.870MHz



n77\_2\_30MHz\_30kHz\_3685MHz\_CP-OFDM 16  
QAM\_RB78@0 27.877MHz



n77\_2\_30MHz\_30kHz\_3685MHz\_CP-OFDM 64  
QAM\_RB78@0 27.754MHz




n77\_2\_30MHz\_30kHz\_3685MHz\_CP-OFDM 256  
QAM\_RB78@0 27.764MHz



n77\_2\_40MHz\_30kHz\_3570MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB100@0 37.512MHz




n77\_2\_40MHz\_30kHz\_3570MHz\_DFT-s-OFDM  
QPSK\_RB100@0 37.620MHz




n77\_2\_40MHz\_30kHz\_3570MHz\_DFT-s-OFDM 16  
QAM\_RB100@0 37.189MHz




n77\_2\_40MHz\_30kHz\_3570MHz\_DFT-s-OFDM 64  
QAM\_RB100@0 37.031MHz



n77\_2\_40MHz\_30kHz\_3570MHz\_DFT-s-OFDM 256  
QAM\_RB100@0 37.304MHz




n77\_2\_40MHz\_30kHz\_3570MHz\_CP-OFDM  
QPSK\_RB106@0 37.812MHz



n77\_2\_40MHz\_30kHz\_3570MHz\_CP-OFDM 16  
QAM\_RB106@0 37.776MHz



n77\_2\_40MHz\_30kHz\_3570MHz\_CP-OFDM 64  
QAM\_RB106@0 37.829MHz




n77\_2\_40MHz\_30kHz\_3570MHz\_CP-OFDM 256  
QAM\_RB106@0 37.764MHz



n77\_2\_40MHz\_30kHz\_3625MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB100@0 37.492MHz



n77\_2\_40MHz\_30kHz\_3625MHz\_DFT-s-OFDM  
QPSK\_RB100@0 37.626MHz



n77\_2\_40MHz\_30kHz\_3625MHz\_DFT-s-OFDM 16  
QAM\_RB100@0 37.318MHz




n77\_2\_40MHz\_30kHz\_3625MHz\_DFT-s-OFDM 64  
QAM\_RB100@0 37.283MHz




n77\_2\_40MHz\_30kHz\_3625MHz\_DFT-s-OFDM 256  
QAM\_RB100@0 37.311MHz



n77\_2\_40MHz\_30kHz\_3625MHz\_CP-OFDM  
QPSK\_RB106@0 37.772MHz




n77\_2\_40MHz\_30kHz\_3625MHz\_CP-OFDM 16  
QAM\_RB106@0 37.801MHz



n77\_2\_40MHz\_30kHz\_3625MHz\_CP-OFDM 64  
QAM\_RB106@0 37.830MHz




n77\_2\_40MHz\_30kHz\_3625MHz\_CP-OFDM 256  
QAM\_RB106@0 37.774MHz




n77\_2\_40MHz\_30kHz\_3680MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB100@0 37.486MHz




n77\_2\_40MHz\_30kHz\_3680MHz\_DFT-s-OFDM  
QPSK\_RB100@0 37.616MHz



n77\_2\_40MHz\_30kHz\_3680MHz\_DFT-s-OFDM 16  
QAM\_RB100@0 37.301MHz




n77\_2\_40MHz\_30kHz\_3680MHz\_DFT-s-OFDM 64  
QAM\_RB100@0 37.191MHz



n77\_2\_40MHz\_30kHz\_3680MHz\_DFT-s-OFDM 256  
QAM\_RB100@0 37.305MHz



n77\_2\_40MHz\_30kHz\_3680MHz\_CP-OFDM  
QPSK\_RB106@0 37.780MHz



n77\_2\_40MHz\_30kHz\_3680MHz\_CP-OFDM 16  
QAM\_RB106@0 37.799MHz



n77\_2\_40MHz\_30kHz\_3680MHz\_CP-OFDM 64  
QAM\_RB106@0 37.813MHz




n77\_2\_40MHz\_30kHz\_3680MHz\_CP-OFDM 256  
QAM\_RB106@0 37.774MHz



n77\_2\_50MHz\_30kHz\_3575MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB128@0 47.039MHz



n77\_2\_50MHz\_30kHz\_3575MHz\_DFT-s-OFDM  
QPSK\_RB128@0 47.228MHz



n77\_2\_50MHz\_30kHz\_3575MHz\_DFT-s-OFDM 16  
QAM\_RB128@0 47.010MHz

