


n77\_2\_100MHz\_30kHz\_3650MHz\_CP-OFDM 16  
QAM\_RB273@0 97.322MHz



n77\_2\_100MHz\_30kHz\_3650MHz\_CP-OFDM 64  
QAM\_RB273@0 97.266MHz




n78\_2

n77\_2\_100MHz\_30kHz\_3650MHz\_CP-OFDM 256  
QAM\_RB273@0 97.302MHz




n78\_2\_10MHz\_30kHz\_3555MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB24@0 8.570MHz




n78\_2\_10MHz\_30kHz\_3555MHz\_DFT-s-OFDM  
QPSK\_RB24@0 8.573MHz




n78\_2\_10MHz\_30kHz\_3555MHz\_DFT-s-OFDM 16  
QAM\_RB24@0 8.575MHz




n78\_2\_10MHz\_30kHz\_3555MHz\_DFT-s-OFDM 64  
QAM\_RB24@0 8.601MHz




n78\_2\_10MHz\_30kHz\_3555MHz\_DFT-s-OFDM 256  
QAM\_RB24@0 8.568MHz




n78\_2\_10MHz\_30kHz\_3555MHz\_CP-OFDM  
QPSK\_RB24@0 8.566MHz




n78\_2\_10MHz\_30kHz\_3555MHz\_CP-OFDM 16  
QAM\_RB24@0 8.571MHz




n78\_2\_10MHz\_30kHz\_3555MHz\_CP-OFDM 64  
QAM\_RB24@0 8.571MHz




n78\_2\_10MHz\_30kHz\_3555MHz\_CP-OFDM 256  
QAM\_RB24@0 8.607MHz




n78\_2\_10MHz\_30kHz\_3625MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB24@0 8.569MHz




n78\_2\_10MHz\_30kHz\_3625MHz\_DFT-s-OFDM  
QPSK\_RB24@0 8.574MHz




n78\_2\_10MHz\_30kHz\_3625MHz\_DFT-s-OFDM 16  
QAM\_RB24@0 8.573MHz




n78\_2\_10MHz\_30kHz\_3625MHz\_DFT-s-OFDM 64  
QAM\_RB24@0 8.539MHz




n78\_2\_10MHz\_30kHz\_3625MHz\_DFT-s-OFDM 256  
QAM\_RB24@0 8.564MHz




n78\_2\_10MHz\_30kHz\_3625MHz\_CP-OFDM  
QPSK\_RB24@0 8.574MHz




n78\_2\_10MHz\_30kHz\_3625MHz\_CP-OFDM 16  
QAM\_RB24@0 8.571MHz




n78\_2\_10MHz\_30kHz\_3625MHz\_CP-OFDM 64  
QAM\_RB24@0 8.569MHz




n78\_2\_10MHz\_30kHz\_3625MHz\_CP-OFDM 256  
QAM\_RB24@0 8.610MHz




n78\_2\_10MHz\_30kHz\_3695MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB24@0 8.570MHz




n78\_2\_10MHz\_30kHz\_3695MHz\_DFT-s-OFDM  
QPSK\_RB24@0 8.574MHz




n78\_2\_10MHz\_30kHz\_3695MHz\_DFT-s-OFDM 16  
QAM\_RB24@0 8.578MHz




n78\_2\_10MHz\_30kHz\_3695MHz\_DFT-s-OFDM 64  
QAM\_RB24@0 8.579MHz




n78\_2\_10MHz\_30kHz\_3695MHz\_DFT-s-OFDM 256  
QAM\_RB24@0 8.568MHz




n78\_2\_10MHz\_30kHz\_3695MHz\_CP-OFDM  
QPSK\_RB24@0 8.577MHz




n78\_2\_10MHz\_30kHz\_3695MHz\_CP-OFDM 16  
QAM\_RB24@0 8.568MHz



n78\_2\_10MHz\_30kHz\_3695MHz\_CP-OFDM 64  
QAM\_RB24@0 8.576MHz




n78\_2\_10MHz\_30kHz\_3695MHz\_CP-OFDM 256  
QAM\_RB24@0 8.611MHz




n78\_2\_15MHz\_30kHz\_3557.5MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB36@0 13.452MHz




n78\_2\_15MHz\_30kHz\_3557.5MHz\_DFT-s-OFDM  
QPSK\_RB36@0 13.399MHz



n78\_2\_15MHz\_30kHz\_3557.5MHz\_DFT-s-OFDM 16  
QAM\_RB36@0 13.562MHz



n78\_2\_15MHz\_30kHz\_3557.5MHz\_DFT-s-OFDM 64  
QAM\_RB36@0 13.461MHz



n78\_2\_15MHz\_30kHz\_3557.5MHz\_DFT-s-OFDM 256  
QAM\_RB36@0 13.450MHz



n78\_2\_15MHz\_30kHz\_3557.5MHz\_CP-OFDM  
QPSK\_RB38@0 13.572MHz

