

n78\_2\_80MHz\_30kHz\_3625MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB216@0 77.213MHz



n78\_2\_80MHz\_30kHz\_3625MHz\_DFT-s-OFDM  
QPSK\_RB216@0 76.933MHz




n78\_2\_80MHz\_30kHz\_3625MHz\_DFT-s-OFDM 16  
QAM\_RB216@0 76.922MHz




n78\_2\_80MHz\_30kHz\_3625MHz\_DFT-s-OFDM 64  
QAM\_RB216@0 76.946MHz



n78\_2\_80MHz\_30kHz\_3625MHz\_DFT-s-OFDM 256  
QAM\_RB216@0 76.880MHz




n78\_2\_80MHz\_30kHz\_3625MHz\_CP-OFDM  
QPSK\_RB217@0 77.270MHz




n78\_2\_80MHz\_30kHz\_3625MHz\_CP-OFDM 16  
QAM\_RB217@0 77.174MHz




n78\_2\_80MHz\_30kHz\_3625MHz\_CP-OFDM 64  
QAM\_RB217@0 77.441MHz



n78\_2\_80MHz\_30kHz\_3625MHz\_CP-OFDM 256  
QAM\_RB217@0 77.503MHz



n78\_2\_80MHz\_30kHz\_3660MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB216@0 77.124MHz



n78\_2\_80MHz\_30kHz\_3660MHz\_DFT-s-OFDM  
QPSK\_RB216@0 76.943MHz



n78\_2\_80MHz\_30kHz\_3660MHz\_DFT-s-OFDM 16  
QAM\_RB216@0 76.890MHz



n78\_2\_80MHz\_30kHz\_3660MHz\_DFT-s-OFDM 64  
QAM\_RB216@0 76.942MHz



n78\_2\_80MHz\_30kHz\_3660MHz\_DFT-s-OFDM 256  
QAM\_RB216@0 76.837MHz



n78\_2\_80MHz\_30kHz\_3660MHz\_CP-OFDM  
QPSK\_RB217@0 77.254MHz



n78\_2\_80MHz\_30kHz\_3660MHz\_CP-OFDM 16  
QAM\_RB217@0 77.153MHz



n78\_2\_80MHz\_30kHz\_3660MHz\_CP-OFDM 64  
QAM\_RB217@0 77.262MHz




n78\_2\_80MHz\_30kHz\_3660MHz\_CP-OFDM 256  
QAM\_RB217@0 77.517MHz



n78\_2\_90MHz\_30kHz\_3595MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB243@0 86.551MHz




n78\_2\_90MHz\_30kHz\_3595MHz\_DFT-s-OFDM  
QPSK\_RB243@0 86.788MHz



n78\_2\_90MHz\_30kHz\_3595MHz\_DFT-s-OFDM 16  
QAM\_RB243@0 86.470MHz




n78\_2\_90MHz\_30kHz\_3595MHz\_DFT-s-OFDM 64  
QAM\_RB243@0 86.771MHz



n78\_2\_90MHz\_30kHz\_3595MHz\_DFT-s-OFDM 256  
QAM\_RB243@0 86.458MHz




n78\_2\_90MHz\_30kHz\_3595MHz\_CP-OFDM  
QPSK\_RB245@0 87.255MHz



n78\_2\_90MHz\_30kHz\_3595MHz\_CP-OFDM 16  
QAM\_RB245@0 87.247MHz



n78\_2\_90MHz\_30kHz\_3595MHz\_CP-OFDM 64  
QAM\_RB245@0 87.214MHz



n78\_2\_90MHz\_30kHz\_3595MHz\_CP-OFDM 256  
QAM\_RB245@0 87.258MHz



n78\_2\_90MHz\_30kHz\_3625MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB243@0 86.532MHz



n78\_2\_90MHz\_30kHz\_3625MHz\_DFT-s-OFDM  
QPSK\_RB243@0 86.881MHz




n78\_2\_90MHz\_30kHz\_3625MHz\_DFT-s-OFDM 16  
QAM\_RB243@0 86.434MHz



n78\_2\_90MHz\_30kHz\_3625MHz\_DFT-s-OFDM 64  
QAM\_RB243@0 86.788MHz



n78\_2\_90MHz\_30kHz\_3625MHz\_DFT-s-OFDM 256  
QAM\_RB243@0 86.765MHz



n78\_2\_90MHz\_30kHz\_3625MHz\_CP-OFDM  
QPSK\_RB245@0 87.221MHz



n78\_2\_90MHz\_30kHz\_3625MHz\_CP-OFDM 16  
QAM\_RB245@0 87.237MHz



n78\_2\_90MHz\_30kHz\_3625MHz\_CP-OFDM 64  
QAM\_RB245@0 87.200MHz



n78\_2\_90MHz\_30kHz\_3625MHz\_CP-OFDM 256  
QAM\_RB245@0 87.500MHz

