



n41\_40MHz\_30kHz\_2516.01MHz\_CP-OFDM 16  
QAM\_RB106@0 37.792MHz



n41\_40MHz\_30kHz\_2516.01MHz\_CP-OFDM 64  
QAM\_RB106@0 37.835MHz



n41\_40MHz\_30kHz\_2516.01MHz\_CP-OFDM 256  
QAM\_RB106@0 37.786MHz




n41\_40MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB100@0 37.502MHz




n41\_40MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB100@0 37.497MHz



n41\_40MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 16  
QAM\_RB100@0 37.334MHz




n41\_40MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 64  
QAM\_RB100@0 37.176MHz




n41\_40MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 256  
QAM\_RB100@0 37.282MHz



n41\_40MHz\_30kHz\_2592.99MHz\_CP-OFDM  
QPSK\_RB106@0 37.671MHz




n41\_40MHz\_30kHz\_2592.99MHz\_CP-OFDM 16  
QAM\_RB106@0 37.792MHz




n41\_40MHz\_30kHz\_2592.99MHz\_CP-OFDM 64  
QAM\_RB106@0 37.826MHz




n41\_40MHz\_30kHz\_2592.99MHz\_CP-OFDM 256  
QAM\_RB106@0 37.773MHz




n41\_40MHz\_30kHz\_2670MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB100@0 37.679MHz




n41\_40MHz\_30kHz\_2670MHz\_DFT-s-OFDM  
QPSK\_RB100@0 37.667MHz




n41\_40MHz\_30kHz\_2670MHz\_DFT-s-OFDM 16  
QAM\_RB100@0 37.515MHz




n41\_40MHz\_30kHz\_2670MHz\_DFT-s-OFDM 64  
QAM\_RB100@0 37.460MHz




n41\_40MHz\_30kHz\_2670MHz\_DFT-s-OFDM 256  
QAM\_RB100@0 37.503MHz



n41\_40MHz\_30kHz\_2670MHz\_CP-OFDM  
QPSK\_RB106@0 37.835MHz




n41\_40MHz\_30kHz\_2670MHz\_CP-OFDM 16  
QAM\_RB106@0 37.820MHz




n41\_40MHz\_30kHz\_2670MHz\_CP-OFDM 64  
QAM\_RB106@0 37.930MHz




n41\_40MHz\_30kHz\_2670MHz\_CP-OFDM 256  
QAM\_RB106@0 37.812MHz



n41\_50MHz\_30kHz\_2521.02MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB128@0 46.860MHz



n41\_50MHz\_30kHz\_2521.02MHz\_DFT-s-OFDM  
QPSK\_RB128@0 46.653MHz




n41\_50MHz\_30kHz\_2521.02MHz\_DFT-s-OFDM 16  
QAM\_RB128@0 47.019MHz




n41\_50MHz\_30kHz\_2521.02MHz\_DFT-s-OFDM 64  
QAM\_RB128@0 46.858MHz




n41\_50MHz\_30kHz\_2521.02MHz\_DFT-s-OFDM 256  
QAM\_RB128@0 47.226MHz




n41\_50MHz\_30kHz\_2521.02MHz\_CP-OFDM  
QPSK\_RB133@0 47.415MHz




n41\_50MHz\_30kHz\_2521.02MHz\_CP-OFDM 16  
QAM\_RB133@0 47.465MHz




n41\_50MHz\_30kHz\_2521.02MHz\_CP-OFDM 64  
QAM\_RB133@0 47.414MHz




n41\_50MHz\_30kHz\_2521.02MHz\_CP-OFDM 256  
QAM\_RB133@0 47.407MHz



n41\_50MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB128@0 46.884MHz




n41\_50MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB128@0 47.265MHz




n41\_50MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 16  
QAM\_RB128@0 47.008MHz



n41\_50MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 64  
QAM\_RB128@0 46.829MHz



n41\_50MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 256  
QAM\_RB128@0 47.070MHz



n41\_50MHz\_30kHz\_2592.99MHz\_CP-OFDM  
QPSK\_RB133@0 47.438MHz

