




n41\_50MHz\_30kHz\_2592.99MHz\_CP-OFDM 16  
QAM\_RB133@0 47.425MHz




n41\_50MHz\_30kHz\_2592.99MHz\_CP-OFDM 64  
QAM\_RB133@0 47.426MHz




n41\_50MHz\_30kHz\_2592.99MHz\_CP-OFDM 256  
QAM\_RB133@0 47.404MHz



n41\_50MHz\_30kHz\_2664.99MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB128@0 47.297MHz




n41\_50MHz\_30kHz\_2664.99MHz\_DFT-s-OFDM  
QPSK\_RB128@0 47.450MHz




n41\_50MHz\_30kHz\_2664.99MHz\_DFT-s-OFDM 16  
QAM\_RB128@0 47.231MHz




n41\_50MHz\_30kHz\_2664.99MHz\_DFT-s-OFDM 64  
QAM\_RB128@0 47.038MHz




n41\_50MHz\_30kHz\_2664.99MHz\_DFT-s-OFDM 256  
QAM\_RB128@0 47.410MHz




n41\_50MHz\_30kHz\_2664.99MHz\_CP-OFDM  
QPSK\_RB133@0 47.459MHz




n41\_50MHz\_30kHz\_2664.99MHz\_CP-OFDM 16  
QAM\_RB133@0 47.466MHz




n41\_50MHz\_30kHz\_2664.99MHz\_CP-OFDM 64  
QAM\_RB133@0 47.454MHz




n41\_50MHz\_30kHz\_2664.99MHz\_CP-OFDM 256  
QAM\_RB133@0 47.416MHz



n41\_60MHz\_30kHz\_2526MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB162@0 57.881MHz




n41\_60MHz\_30kHz\_2526MHz\_DFT-s-OFDM  
QPSK\_RB162@0 57.857MHz



n41\_60MHz\_30kHz\_2526MHz\_DFT-s-OFDM 16  
QAM\_RB162@0 57.634MHz



n41\_60MHz\_30kHz\_2526MHz\_DFT-s-OFDM 64  
QAM\_RB162@0 57.956MHz



n41\_60MHz\_30kHz\_2526MHz\_DFT-s-OFDM 256  
QAM\_RB162@0 57.662MHz



n41\_60MHz\_30kHz\_2526MHz\_CP-OFDM  
QPSK\_RB162@0 57.685MHz




n41\_60MHz\_30kHz\_2526MHz\_CP-OFDM 16  
QAM\_RB162@0 57.697MHz




n41\_60MHz\_30kHz\_2526MHz\_CP-OFDM 64  
QAM\_RB162@0 57.850MHz



n41\_60MHz\_30kHz\_2526MHz\_CP-OFDM 256  
QAM\_RB162@0 57.878MHz




n41\_60MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB162@0 57.702MHz



n41\_60MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB162@0 57.608MHz




n41\_60MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 16  
QAM\_RB162@0 57.477MHz



n41\_60MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 64  
QAM\_RB162@0 57.887MHz



n41\_60MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 256  
QAM\_RB162@0 57.473MHz




n41\_60MHz\_30kHz\_2592.99MHz\_CP-OFDM  
QPSK\_RB162@0 57.682MHz




n41\_60MHz\_30kHz\_2592.99MHz\_CP-OFDM 16  
QAM\_RB162@0 57.667MHz




n41\_60MHz\_30kHz\_2592.99MHz\_CP-OFDM 64  
QAM\_RB162@0 57.708MHz




n41\_60MHz\_30kHz\_2592.99MHz\_CP-OFDM 256  
QAM\_RB162@0 57.627MHz




n41\_60MHz\_30kHz\_2659.98MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB162@0 57.937MHz




n41\_60MHz\_30kHz\_2659.98MHz\_DFT-s-OFDM  
QPSK\_RB162@0 57.848MHz



n41\_60MHz\_30kHz\_2659.98MHz\_DFT-s-OFDM 16  
QAM\_RB162@0 57.673MHz



n41\_60MHz\_30kHz\_2659.98MHz\_DFT-s-OFDM 64  
QAM\_RB162@0 57.925MHz



n41\_60MHz\_30kHz\_2659.98MHz\_DFT-s-OFDM 256  
QAM\_RB162@0 57.676MHz



n41\_60MHz\_30kHz\_2659.98MHz\_CP-OFDM  
QPSK\_RB162@0 57.693MHz

