

## Audit Mode Request Letter

TIMCO Engineering, Inc.

Some errors found in the spot check report by JYT and request to update the original reports,  
This is to request audit mode of FCC ID: 2AF82-TD1050HPRO,

The updated reports which we will upload after audit mode.

The major change filed under this application and the relevant report numbers can be referred to  
the "Report Revision Explanation Letter form JYT\_FCC ID 2AF82-TD1050HPRO".

Sincerely,



(signature)

(printed name) Jim Huang