



LISTED
E365015
Temp. Ind. & Reg. Equip.



SunTouch
SunStat R4 Relay

GFCI CLASS A Jul 2015
1140-01 Lot 12345
Designed and assembled
in Canada

CAUTION:
High Voltage - disconnect power supply before servicing. To reduce the risk of electrical shock - do not connect to a circuit operating at more than 150 V to ground.

ATTENTION
Haute tension - débranchez la source d'alimentation avant un travail de maintenance. Pour réduire les risques d'électrocution choc - ne pas raccorder à un circuit fonctionnant à plus de 150 V à la terre.

Meets CAN ICES-3 (B)/NMB-3(B), FCC Part 15B;
FCC ID: 2AFJT-11400A
IC: 20938-11400A

RELAY (B)
COM (A)
RELAY (B)
COM (A)

Notes:

Caution/Attention must be at least 1/8" high. Remaining warning text must be at least 1/16" high.

Revision Table				
Rev #	Description	Date	Revision By	Approved
1	Initial Release	10/06/2020	GB	
2	Removed Rear Label Artwork	11/12/2020	BK	
3	Adjusted name to Sunstat R4 Relay	03/25/2021	BK	
4	Adjusted Label to fit FCC Text, and outline	04/23/2021	GB	
5	Added final FCC and IC IDs	06/17/2021	GB	

tekmar Control Systems Ltd.		
Part N°:	Part Rev: 4	Drawing Version: 4
114001 SunStat Connect Labels		
Drawn by: GB	Scale: 1x	Date: April 23, 2021
The information and drawings contained herein are the sole property of tekmar Control Systems Ltd. and shall not be disclosed to 3rd parties without the express written consent of tekmar.		