

# Internal Photos Documentation

Manufacturer: Rollease Acmeda Inc


Product: Tubular Motor

FCC ID: 2AGGZ003B9ACA5E

IC: 21769-003B9ACA5E

Model: MT01-1335-069002

Page 1 of 7



# Internal Photos Documentation

Manufacturer: Rollease Acmeda Inc



Product: Tubular Motor

FCC ID: 2AGGZ003B9ACA5E

IC: 21769-003B9ACA5E

Model: MT01-1335-069002



Page 2 of 7



# Internal Photos Documentation

Manufacturer: Rollease Acmeda Inc  
Product: Tubular Motor  
FCC ID: 2AGGZ003B9ACA5E  
IC: 21769-003B9ACA5E  
Model: MT01-1335-069002

Page 3 of 7



# Internal Photos Documentation

Manufacturer: Rollease Acmeda Inc



Product: Tubular Motor

FCC ID: 2AGGZ003B9ACA5E

IC: 21769-003B9ACA5E

Model: MT01-1335-069002

Page 4 of 7



# Internal Photos Documentation

Manufacturer: Rollease Acmeda Inc



Product: Tubular Motor

FCC ID: 2AGGZ003B9ACA5E

IC: 21769-003B9ACA5E

Model: MT01-1335-069002

Page 5 of 7



# Internal Photos Documentation

Manufacturer: Rollease Acmeda Inc



Product: Tubular Motor

FCC ID: 2AGGZ003B9ACA5E

IC: 21769-003B9ACA5E

Model: MT01-1335-069002

Page 6 of 7



# Internal Photos Documentation

Manufacturer: Rollease Acmeda Inc

Product: Tubular Motor

FCC ID: 2AGGZ003B9ACA5E

IC: 21769-003B9ACA5E

Model: MT01-1335-069002

Page 7 of 7

