

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2AHFE-UFCV1000
21143-UFCV1000
19-0040
March 18, 2019
Reliance Worldwide Corporation
UFCV-1000

INTERNAL PHOTOGRAPHS




Figure 1. EUT, Inside Enclosure

US Tech Test Report:

FCC ID:

IC:

Test Report Number:

Issue Date:

Customer:

Model:

FCC Part 15/IC RSS Certification

2AHFE-UFCV1000

21143-UFCV1000

19-0040

March 18, 2019

Reliance Worldwide Corporation

UFCV-1000




Figure 2. Radio PCB, Top View

US Tech Test Report:

FCC ID:

IC:

Test Report Number:

Issue Date:

Customer:

Model:

FCC Part 15/IC RSS Certification

2AHFE-UFCV1000

21143-UFCV1000

19-0040

March 18, 2019

WIDEWORLD, LTD.

UFCV-1000




Figure 3. Radio PCB, Bottom View

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2AHFE-UFCV1000
21143-UFCV1000
19-0040
March 18, 2019
Reliance Worldwide Corporation
UFCV-1000




Figure 4. Meter Board, Top View

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2AHFE-UFCV1000
21143-UFCV1000
19-0040
March 18, 2019
Reliance Worldwide Corporation
UFCV-1000




Figure 5. Meter Board, Bottom View

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2AHFE-UFCV1000
21143-UFCV1000
19-0040
March 18, 2019
Reliance Worldwide Corporation
UFCV-1000




Figure 6. Shutoff Valve Board, Top View

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2AHFE-UFCV1000
21143-UFCV1000
19-0040
March 18, 2019
Reliance Worldwide Corporation
UFCV-1000




Figure 7. Shutoff Valve Board, Bottom View

US Tech Test Report:

FCC ID:

IC:

Test Report Number:

Issue Date:

Customer:

Model:

FCC Part 15/IC RSS Certification

2AHFE-UFCV1000

21143-UFCV1000

19-0040

March 18, 2019

Reliance Worldwide Corporation

UFCV-1000




Figure 8. Sensor Interface Board, Top View

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2AHFE-UFCV1000
21143-UFCV1000
19-0040
March 18, 2019
Reliance Worldwide Corporation
UFCV-1000




Figure 9. Sensor Interface Board, Bottom View

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2AHFE-UFCV1000
21143-UFCV1000
19-0040
March 18, 2019
Reliance Worldwide Corporation
UFCV-1000




Figure 10. Internal Wiring 1

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2AHFE-UFCV1000
21143-UFCV1000
19-0040
March 18, 2019
Reliance Worldwide Corporation
UFCV-1000




Figure 11. Internal Wiring 2

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2AHFE-UFCV1000
21143-UFCV1000
19-0040
March 18, 2019
Reliance Worldwide Corporation
UFCV-1000




Figure 12. Temperature and Humidity Sensor Board, Top View

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2AHFE-UFCV1000
21143-UFCV1000
19-0040
March 18, 2019
Reliance Worldwide Corporation
UFCV-1000




Figure 13. Temperature and Humidity Sensor Board, Bottom View