

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
2AHQD-SENSOR4
22-0125
June 6, 2022
Clean Hand Safe Hands, LLC
Sensor4

INTERNAL PHOTOGRAPHS



**Figure 1. Mounting wall plate removed
(Back of EUT exposed)**

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
2AHQD-SENSOR4
22-0125
June 6, 2022
Clean Hand Safe Hands, LLC
Sensor4




Figure 2. Close up of Battery

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
2AHQD-SENSOR4
22-0125
June 6, 2022
Clean Hand Safe Hands, LLC
Sensor4




Figure 3. Back Cover Removed

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
2AHQD-SENSOR4
22-0125
June 6, 2022
Clean Hand Safe Hands, LLC
Sensor4



Figure 4. Close up of Speaker

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
2AHQD-SENSOR4
22-0125
June 6, 2022
Clean Hand Safe Hands, LLC
Sensor4



Figure 5. Back of Board

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
2AHQD-SENSOR4
22-0125
June 6, 2022
Clean Hand Safe Hands, LLC
Sensor4




Figure 6. Front of Board

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
2AHQD-SENSOR4
22-0125
June 6, 2022
Clean Hand Safe Hands, LLC
Sensor4




Figure 7. Close up of Bluetooth Module

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
2AHQD-SENSOR4
22-0125
June 6, 2022
Clean Hand Safe Hands, LLC
Sensor4

