

Attn: Reviewing Engineer
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Brose Fahrzeugteile
SE & Co.
Kommanditgesellschaft,
Bamberg

HVIN:	FCC Certification Number:	Approval Date:
Door Control System	2AHV8-C31859	08/24/2017

Application to Class II Permissive Change

This request is to add new module versions to the FCC ID 2AHV8-C31859. The difference between the new module versions and the already certified version is described below.

Explanation:

Software: The function of roof hatch at passenger side is not available anymore.

Hardware: In general, functionally, there is no difference (beside the software named function). Components have been replaced by components in order to increase the market availability (RF Switch, RF Resonator / Quarz, Voltage regulator, Tranceiver).

Thank you for your attention in this matter.

Yours Sincerely,

27.Jul.2021



Berliner Ring 1
D-96052 Bamberg

Phone: +49 951 7474 0
Fax: +49 951 7474 1812

E-Mail: bamberg@brose.com
Internet: www.brose.com

Standort Hallstadt:
Max-Brose-Straße 2
D-96103 Hallstadt

Phone: +49 951 7474 0
Fax: +49 951 7474 4123

E-Mail: hallstadt@brose.com
Internet: www.brose.com

Sitz der Gesellschaft Bamberg
Reg.-Gericht Bamberg
HRA 9499
USt.-Id. Nr. DE 132444708

Komplementär:
Brose Verwaltung SE, Bamberg
Sitz Bamberg, Reg.-Gericht
Bamberg HRB 9754

Geschäftsführende Direktoren:
Ulrich Schrickel (Vorsitzender)
Niklas Beyes
Periklis Nassios
Christof Vollkommer
Dr. Michael Swoboda
(Werkleitung)

Vorsitzender des
Verwaltungsrats:
Michael Stoschek