





Shenzhen Microtest Co., Ltd.

1. Did a test Firm or third party (other than the certification body and applicant) provide a list of software installed on the device and after scan results with no evidence of Kaspersky software.



Note: Reference video file and the following screenshots






Shenzhen Microtest Co., Ltd.






Shenzhen Microtest Co., Ltd.






Shenzhen Microtest Co., Ltd.





Shenzhen Microtest Co., Ltd.



Shenzhen Microtest Co., Ltd.





Shenzhen Microtest Co., Ltd.




2. Has other objective evidence been provided that no Kaspersky software is installed.

Shenzhen Microtest Co., Ltd.



Shenzhen Microtest Co., Ltd.



Sincerely/*Leon Chen*

Name / Title: Leon Chen / Technical director

Company Name: Shenzhen Microtest Co., Ltd

Address: 101, No. 7, Zone 2, Xinxing Industrial Park, Fuhai Avenue, Xinhe Community,
Fuhai Street, Bao' an District, Shenzhen, Guangdong, China

Tel: +86-755 88850135

E-Mail: leon@51mti.com