





installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

FCC ID: 2AIXC-RBKF-TWS

 <p>RBKF1302-PPNK 6 81066 15254 6 MID#2750425 Made in China</p>	<p>2025 CSI Edison NJ 08817</p> 	<p>CONTENTS: Sport True Wireless Earphones Charging Case USB-C Charging Cable User Manual</p> <p>Keep manual and all relevant information for future reference.</p>	<p>The Bluetooth® word mark and logos are registered trademarks owned by the Bluetooth SIG, Inc. and any use of such marks by Sakar International. is under license. Other trademarks and trade names are those of their respective owners.</p>
<p>© Reebok International Limited, All rights reserved. Reebok® and  are trademarks of Reebok International Limited.</p>			<p>FCC ID: 2AIXC-RBKF-TWS</p>
<p> WARNING: Cancer and Reproductive Harm - www.P65Warnings.ca.gov</p>			

The FCC ID is in the user manual due to the size of the device and the FCC ID is included on the device packaging.