


n38_30MHz_30kHz_2595MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0



n38_30MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB75@0



n38_30MHz_30kHz_2595MHz_DFT-s-OFDM 16 QAM_RB75@0



n38_30MHz_30kHz_2595MHz_DFT-s-OFDM 64
QAM_RB75@0



n38_30MHz_30kHz_2595MHz_DFT-s-OFDM 256
QAM_RB75@0



n38_30MHz_30kHz_2595MHz_CP-OFDM QPSK_RB78@0



n38_30MHz_30kHz_2595MHz_CP-OFDM 16 QAM_RB78@0



n38_30MHz_30kHz_2595MHz_CP-OFDM 64 QAM_RB78@0



n38_30MHz_30kHz_2595MHz_CP-OFDM 256 QAM_RB78@0



n38_40MHz_30kHz_2595MHz_DFT-s-OFDM $\pi/2$ BPSK_RB100@0



n38_40MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB100@0



n38_40MHz_30kHz_2595MHz_DFT-s-OFDM 16 QAM_RB100@0




n38_40MHz_30kHz_2595MHz_DFT-s-OFDM 64
QAM_RB100@0



n38_40MHz_30kHz_2595MHz_DFT-s-OFDM 256
QAM_RB100@0



n38_40MHz_30kHz_2595MHz_CP-OFDM QPSK_RB106@0



n38_40MHz_30kHz_2595MHz_CP-OFDM 16 QAM_RB106@0



n38_40MHz_30kHz_2595MHz_CP-OFDM 64 QAM_RB106@0




n38_40MHz_30kHz_2595MHz_CP-OFDM 256 QAM_RB106@0




n41


n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB24@0




n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB24@0




n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB24@0




n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB24@0




n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB24@0




n41_10MHz_30kHz_2592.99MHz_CP-OFDM QPSK_RB24@0




n41_10MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB24@0



n41_10MHz_30kHz_2592.99MHz_CP-OFDM 64 QAM_RB24@0



n41_10MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB24@0



n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB36@0



n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB36@0



n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB36@0



n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB36@0



n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB36@0



n41_15MHz_30kHz_2592.99MHz_CP-OFDM QPSK_RB38@0



n41_15MHz_30kHz_2592.99MHz_CP-OFDM 16 QAM_RB38@0



n41_15MHz_30kHz_2592.99MHz_CP-OFDM 64 QAM_RB38@0



n41_15MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB38@0



n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0




n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB50@0



n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB50@0



n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB50@0



n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB50@0



n41_20MHz_30kHz_2592.99MHz_CP-OFDM QPSK_RB51@0




n41_20MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB51@0



n41_20MHz_30kHz_2592.99MHz_CP-OFDM 64 QAM_RB51@0



n41_20MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB51@0



n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0



n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB75@0



n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB75@0



n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB75@0




n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB75@0



n41_30MHz_30kHz_2592.99MHz_CP-OFDM QPSK_RB78@0



n41_30MHz_30kHz_2592.99MHz_CP-OFDM 16 QAM_RB78@0



n41_30MHz_30kHz_2592.99MHz_CP-OFDM 64 QAM_RB78@0



n41_30MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB78@0



n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0



n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB100@0



n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB100@0



n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB100@0



n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB100@0



n41_40MHz_30kHz_2592.99MHz_CP-OFDM QPSK_RB106@0



n41_40MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB106@0



n41_40MHz_30kHz_2592.99MHz_CP-OFDM 64 QAM_RB106@0



n41_40MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB106@0



n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB128@0



n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB128@0



n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB128@0




n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB128@0




n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB128@0



n41_50MHz_30kHz_2592.99MHz_CP-OFDM QPSK_RB133@0



n41_50MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB133@0



n41_50MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB133@0



n41_50MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB133@0



n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB162@0



n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB162@0



n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB162@0



n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB162@0



n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB162@0



n41_60MHz_30kHz_2592.99MHz_CP-OFDM QPSK_RB162@0



n41_60MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB162@0



n41_60MHz_30kHz_2592.99MHz_CP-OFDM 64 QAM_RB162@0



n41_60MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB162@0



n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB216@0



n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB216@0



n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB216@0



n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB216@0



n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB216@0



n41_80MHz_30kHz_2592.99MHz_CP-OFDM QPSK_RB217@0



n41_80MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB217@0



n41_80MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB217@0



n41_80MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB217@0



n41_90MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB243@0



n41_90MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB243@0



n41_90MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB243@0



n41_90MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB243@0



n41_90MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB243@0



n41_90MHz_30kHz_2592.99MHz_CP-OFDM QPSK_RB245@0



n41_90MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB245@0



n41_90MHz_30kHz_2592.99MHz_CP-OFDM 64 QAM_RB245@0



n41_90MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB245@0



n41_100MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB270@0



n41_100MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB270@0



n41_100MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB270@0

