



Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 19:42:16

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 29.MAR.2022 19:42:42

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 19:43:14

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 29.MAR.2022 19:43:37

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 19:44:12

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 29.MAR.2022 19:44:38

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 19:45:11

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 29.MAR.2022 19:45:36

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 19:46:01

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 29.MAR.2022 19:46:17

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 19:46:44

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 29.MAR.2022 19:47:16

Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 20:10:32

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 20:10:51

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 20:11:21

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 20:11:43

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 20:12:06

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 20:12:25

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 20:12:57

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 20:13:20

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 20:13:47

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 20:14:16

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 20:14:43

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 20:15:09

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 20:15:45

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 20:16:14

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 20:16:50

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 20:17:09

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 20:17:48

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 20:18:13

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.MAR.2022 20:18:50

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 20:19:13

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.MAR.2022 20:19:48

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 20:20:11

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.MAR.2022 20:20:37

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 20:21:06

Band 38_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.MAR.2022 09:27:34

Band 38_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 09:27:58

Band 38_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.MAR.2022 09:28:24

Band 38_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 09:28:54

Band 38_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.MAR.2022 09:29:27

Band 38_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 09:29:48

Band 38_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.MAR.2022 09:30:21

Band 38_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 09:30:41

Band 38_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.MAR.2022 09:31:16

Band 38_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 09:31:49

Band 38_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.MAR.2022 09:32:17

Band 38_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 09:32:40

Band 38_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.MAR.2022 09:33:16

Band 38_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 09:33:50

Band 38_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.MAR.2022 09:34:23

Band 38_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 09:34:46

Band 38_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.MAR.2022 09:35:23

Band 38_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 09:35:50

Band 38_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.MAR.2022 09:36:29

Band 38_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 09:36:59

Band 38_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.MAR.2022 09:37:32

Band 38_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 09:38:10

Band 38_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.MAR.2022 09:38:40

Band 38_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 09:39:04

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.MAR.2022 10:20:19

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 10:20:45

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.MAR.2022 10:21:18

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 10:21:46

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.MAR.2022 10:22:13

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 10:22:40

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.MAR.2022 10:23:12

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 10:23:36

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.MAR.2022 10:24:04

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 10:24:38

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.MAR.2022 10:25:06

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 10:25:33

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.MAR.2022 10:26:10

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 10:26:40

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.MAR.2022 10:27:15

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 10:27:45

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.MAR.2022 10:28:22

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 10:28:55

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.MAR.2022 10:29:30

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 10:29:58

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.MAR.2022 10:30:41

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 11.MAR.2022 10:31:18

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 11.MAR.2022 10:31:52

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 11.MAR.2022 10:32:21