



DUT and SAR Set-up Photos

Photograph 1: Overall Dimensions of WS50



Photograph 2: Overall Dimensions of WB50



Photograph 3: Front View of the WS50



Photograph 4: Rear View of the WS50



Photograph 5: Front View of the WB50



Photograph 6: Rear View of the WB50



Photograph 7: Front View of the WD50 Accessory




Photograph 8: Rear View of the WD50 Accessory




Extremity Exposure Conditions

Photograph 9: Extremity, Back, 0 mm, WS50



Photograph 10: Extremity, Back, 0 mm, WB50



Photograph 11: Extremity, Back, 0 mm, WS50 and WB50



Photograph 12: Extremity, Back, 0 mm, WS50 and WD50

