



Annex C Internal photographs




180889_5.jpg: MGB2-L2-MLI-U-Y0000-BJ-156392, internal view 1 (top covers removed)

Annex C Internal photographs




180889_6.jpg: MGB2-L2-MLI-U-Y0000-BJ-156392, internal view 2 (bottom cover removed)

Annex C Internal photographs




180889_4.jpg: MGB2-L2-MLI-U-Y0000-BJ-156392, internal view 3 (PCB removed)

Annex C Internal photographs




180889_9.jpg: MGB2-L2-MLI-U-Y0000-BJ-156392, PCB, top view

Annex C Internal photographs



180889_10.jpg: MGB2-L2-MLI-U-Y0000-BJ-156392, PCB, bottom view

Annex C Internal photographs




180889_18.jpg: MGB2-L1-MLI-U-Y0000-BJ-136776, internal view 1 (top covers removed)

Annex C Internal photographs




180889_19.jpg: MGB2-L1-MLI-U-Y0000-BJ-136776, internal view 2 (bottom cover removed)

Annex C Internal photographs




180889_20.jpg: MGB2-L1-MLI-U-Y0000-BJ-136776, internal view 3 (PCB removed)

Annex C Internal photographs




180889_21.jpg: MGB2-L1-MLI-U-Y0000-BJ-136776, PCB, top view

Annex C Internal photographs




180889_22.jpg: MGB2-L1-MLI-U-Y0000-BJ-136776, PCB, bottom view

Annex C Internal photographs




180889_13.jpg: MGB2-H-BA1A3-R-136691, internal view

Annex C Internal photographs



180889_23.jpg: MGB2-L2-MLI-U-Y0000-BJ-156392 with MGB2-H-BA1A3-R-136691

Annex C Internal photographs



180889_24.jpg: MGB2-L1-MLI-U-Y0000-BJ-136776 with MGB2-H-BA1A3-R-136691