



2230 Bandmate Way, Suite 500
Raleigh, NC 27607

www.relaypro.com

February 19, 2025

Attestation

We, Relay, Inc., attest the followings for our device FCC ID: 2AMBHRY2267

- a. The equipment only punctures to optimize network performance and never to avoid licensed Incumbents.
- b. If a licensed incumbent is detected, the equipment will either use bandwidth reduction or a complete move of the channel for avoidance.
- c. If a channel is punctured in order to optimize network performance, it will continue to use CBP in the punctured region.

A handwritten signature in black ink, appearing to read "Michael DiVerde".

Name: Michael DiVerde

E-mail: mdiverde@relaypro.com