




5MHz_Low_QPSK_1@0




5MHz_Low_QPSK_25@0




5MHz_Low_16QAM_1@0




5MHz_Low_16QAM_25@0




5MHz_High_QPSK_1@24




5MHz_High_QPSK_25@0




5MHz_High_16QAM_1@24




5MHz_High_16QAM_25@0




10MHz_Low_QPSK_1@0




10MHz_Low_QPSK_50@0




10MHz_Low_16QAM_1@0




10MHz_Low_16QAM_25@0




10MHz_High_QPSK_1@49




10MHz_High_QPSK_50@0




10MHz_High_16QAM_1@49




10MHz_High_16QAM_25@25




15MHz_Low_QPSK_1@0




15MHz_Low_QPSK_75@0




15MHz_Low_16QAM_1@0




15MHz_Low_16QAM_25@0




15MHz_High_QPSK_1@74




15MHz_High_QPSK_75@0




15MHz_High_16QAM_1@74




15MHz_High_16QAM_25@50




20MHz_Low_QPSK_1@0




20MHz_Low_QPSK_100@0




20MHz_Low_16QAM_1@0




20MHz_Low_16QAM_25@0



20MHz_High_QPSK_1@99





20MHz_High_QPSK_100@0



20MHz_High_16QAM_1@99

20MHz_High_16QAM_25@75




Spurious Emissions at Antenna Terminal

FCC Part 22H


Band 5, Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 09:37:37

1.4MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 09:37:54

1.4MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 09:38:10

3MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 09:40:52

3MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 09:41:09

3MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 09:41:25


5MHz_Low_QPSK_1@0(30MHz~9.49GHz)




5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




5MHz_High_QPSK_1@0(30MHz~9.49GHz)




10MHz_Low_QPSK_1@0(30MHz~9.49GHz)



10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)



10MHz_High_QPSK_1@0(30MHz~9.49GHz)




FCC Part 24E


Band 2, Normal

1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~20.1GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




1.4MHz_High_QPSK_1@0(30MHz~20.1GHz)




3MHz_Low_QPSK_1@0(30MHz~20.1GHz)




3MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




3MHz_High_QPSK_1@0(30MHz~20.1GHz)




5MHz_Low_QPSK_1@0(30MHz~20.1GHz)




5MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




5MHz_High_QPSK_1@0(30MHz~20.1GHz)




10MHz_Low_QPSK_1@0(30MHz~20.1GHz)




10MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




10MHz_High_QPSK_1@0(30MHz~20.1GHz)




15MHz_Low_QPSK_1@0(30MHz~20.1GHz)




15MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




15MHz_High_QPSK_1@0(30MHz~20.1GHz)




20MHz_Low_QPSK_1@0(30MHz~20.1GHz)



20MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




20MHz_High_QPSK_1@0(30MHz~20.1GHz)



FCC Part 27


Band 4, Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 09:07:04

1.4MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 09:07:25

1.4MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 09:07:46

3MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 09:09:32

3MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 09:09:53

3MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 09:10:14


5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




5MHz_High_QPSK_1@0(30MHz~18.55GHz)




10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




10MHz_High_QPSK_1@0(30MHz~18.55GHz)




15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




15MHz_High_QPSK_1@0(30MHz~18.55GHz)




20MHz_Low_QPSK_1@0(30MHz~18.55GHz)



20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




20MHz_High_QPSK_1@0(30MHz~18.55GHz)




Band 7, Normal
 1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
 Date: 11.FEB.2025 09:49:00

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
 Date: 11.FEB.2025 09:49:20

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
 Date: 11.FEB.2025 09:49:41

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
 Date: 11.FEB.2025 09:51:49

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
 Date: 11.FEB.2025 09:52:31

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
 Date: 11.FEB.2025 09:53:14


15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




15MHz_High_QPSK_1@0(30MHz~26.7GHz)




20MHz_Low_QPSK_1@0(30MHz~26.7GHz)



20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




20MHz_High_QPSK_1@0(30MHz~26.7GHz)




Band 66, Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 10:01:37

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 10:01:57

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 10:02:16

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 10:02:38

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 10:02:57

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 10:03:16


5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




5MHz_High_QPSK_1@0(30MHz~18.8GHz)




10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



10MHz_High_QPSK_1@0(30MHz~18.8GHz)




15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 10:06:33

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 10:07:11

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 10:07:49

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 10:08:30

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 10:09:08

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2502P22282E-RF Tester:Loge Long
Date: 11.FEB.2025 10:09:48

***** END *****