



PANTONE 877 C

NOTES:

1. (xx.xx) INDICATES KEY INSPECTION DIMENSION.
2. TOOLING SHALL BE PERMANENTLY MARKED "PROPERTY OF NURA"
3. MATERIALS MUST BE ROHS AND REACH COMPLIANT

CUT		Marking	
Crease		Kiss cut	
V-mitter		Reference	
Center Line		Pref cut	
Wave		Adhesion	
Amendment		Fixed position	

SCALE 1:1 A3 Dimensions in Millimeters

Circled Dimensions  
On Drawing  
MUST BE INSPECTED  
Drg No. : 1 of 1

Dimensional Tolerances,  
Unless Otherwise Stated Are:  
Two Decimal Places= +/-0.05  
One Decimal Place= +/-0.1  
Zero Decimal Places= +/-0.5

Description:TBA

Part No. : NUR03-920-Certifications Sticker