

Test Setup Photographs for the Smart Torque Tools

1. Radiated Emissions

1.1. Configuration 1: Measurement up to 1 GHz

Photo 1





Photo 2



Radiated Emissions (continued)

1.2. Configuration 1: Measurement above 1 GHz

Photo 3





Photo 4



Conducted Measurement

Photo 5

