

Jody House

From: Kyle McMullan
Sent: Tuesday, June 7, 2022 8:30 AM
To: Jody House
Subject: TRPA0008 Test Mode at 50% DC

Hello Jody,

For testing for TRPA0008, some of the spurious testing was done at 100% DC and some of the spurious testing as done at 50% DC.

The reason why is because there were concerns about overheating when 100% DC was used. Since the EUT spurious emissions were close to the limit, the DC was limited and a DCCF applied to ensure that there wasn't a false failure or a false pass.

Thanks,
[ElementSignature]