





Test report No. : 4788387996A-US-R2-V0
Page : 1 of 4
Issued date : May 28, 2018
FCC ID : 2AO4FM020-1

1. Radiated Measurement Setup Configuration

Z-axis 30-1000MHz Front



Z-axis 30-1000MHz Back



Underwriters Laboratories Taiwan Co., Ltd.


Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan
Telephone : +886-2-7737-3000
Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0875 / 1.0




Test report No. : 4788387996A-US-R2-V0
Page : 2 of 4
Issued date : May 28, 2018
FCC ID : 2AO4FM020-1

Z-axis 9kHz-30MHz Front



Z-axis 9kHz-30MHz Back



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan
Telephone : +886-2-7737-3000
Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0875 / 1.0



Test report No. : 4788387996A-US-R2-V0
Page : 3 of 4
Issued date : May 28, 2018
FCC ID : 2AO4FM020-1

2. Conducted Emission Measurement Setup Configurations



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0875 / 1.0



Test report No. : 4788387996A-US-R2-V0
Page : 4 of 4
Issued date : May 28, 2018
FCC ID : 2AO4FM020-1



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan
Telephone : +886-2-7737-3000
Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0875 / 1.0