

Date

Dec. 12, 2018

Federal Communications Commission  
Office of Engineering and Technology  
445 12<sup>th</sup> ST SW  
Washington, DC 20554

RE: Request for Change in ID

<Original Grantee Holder Anker Innovations Limited> Original FCC ID: <**2AOKB-A2518**>

Original Grant Date: <Nov. 19, 2018>

<New Grantee Holder Anker Innovations Limited> New FCC ID: <**2AOKBA2518**>

To Whom It May Concern:

<New Grantee Holder Anker Innovations Limited> verifies the equipment bearing the modified identification does not differ from the original equipment, there are no differences in terms of both hardware and software. The only difference is the FCC ID number: the FCC ID of original equipment has a symbol “-”, which is deleted in the FCC ID of the equipment bearing the changed identification <New Grantee Holder Anker Innovations Limited>. Our engineer used to add a symbol “-” between Grantee Code and Product Code, but the customers didn't actually need it, and they have already printed the logo, so we needed to change the ID number.

The original test results continue to be representative of and applicable to the equipment bearing the changed identification.

If you required any additional information, please contact us.

Regards,

Signature



New Grantee Holder Contact Name	Simon Zhang
New Grantee Holder Company Name	Anker Innovations Limited
Phone:	0731-88709535
Fax:	0731-88709538
Email:	Simon.zhang@oceanwing.com