



Internal Photos of EUT

Report No.: STS1806066W01

Model No. : C525BU, C225BU

Page: 1 of 11




Internal Photos of EUT

Report No.: STS1806066W01

Model No. : C525BU, C225BU

Page: 2 of 11





Internal Photos of EUT

Report No.: STS1806066W01

Model No. : C525BU, C225BU

Page: 3 of 11





Internal Photos of EUT

Report No.: STS1806066W01

Model No. : C525BU, C225BU

Page: 4 of 11





Internal Photos of EUT

Report No.: STS1806066W01

Model No. : C525BU, C225BU

Page: 5 of 11



Internal Photos of EUT

Report No.: STS1806066W01

Model No. : C525BU, C225BU

Page: 6 of 11





Internal Photos of EUT

Report No.: STS1806066W01

Model No. : C525BU, C225BU

Page: 7 of 11



Internal Photos of EUT

Report No.: STS1806066W01

Model No. : C525BU, C225BU

Page: 8 of 11





Internal Photos of EUT

Report No.: STS1806066W01

Model No. : C525BU, C225BU

Page: 9 of 11




Internal Photos of EUT

Report No.: STS1806066W01

Model No. : C525BU, C225BU

Page: 10 of 11




Internal Photos of EUT

Report No.: STS1806066W01

Model No. : C525BU, C225BU

Page: 11 of 11



--THE END--