


External photographs Module only, Solder Side




Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Cargt, Inc.
Model: MUR1LVUFL
Test: 190324
Test to: CFR47 15C
File: MUR1LVUFL ExtPho


FCC ID: 2AQ2Q-MUR1LVUFL

Date: May 6, 2020
Page 1 of 4



Module Only, cover removed

Module Placed on Development Circuit Board




Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Cargt, Inc.
Model: MUR1LVUFL
Test: 190324
Test to: CFR47 15C
File: MUR1LVUFL ExtPho

FCC ID: 2A22Q-MUR1LVUFL

Date: May 6, 2020
Page 3 of 4



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Cargt, Inc.
Model: MUR1LVUFL
Test: 190324
Test to: CFR47 15C
File: MUR1LVUFL ExtPho

FCC ID: 2AQ2Q-MUR1LVUFL

Date: May 6, 2020
Page 4 of 4