

AEROPRO™ SYSTEM PARTS AND DESCRIPTION

1. Charging Station



2. Motor Component/Power Supply (Motor and Battery)

Adapter

Converts AC current into DC current required for charging the AeroPro™ Cordless handpiece.

Power Supply manufacturer:

Shenzhen Ri Hua Da
Electronic Co., Ltd

Power Supply Model Number:

RHD20W12010000U

Input: 100-240V~50/60Hz; 0.7A

Output: 12V – 1000mA



4. Stand

Provides a passive support for the AeroPro™ handpiece on the tray when not in use. It is fully steam autoclavable. **Note: The autoclavable Stand is a separate component from the non-autoclavable Charging Station.**



5. O-Ring Replacement Kit

There is one O-ring on the Motor Component, and two O-rings on the outer sheath. The O-rings are consumable parts. O-rings can be replaced as needed. A pack of O-rings and a replacement tool is included in the package. It is recommended to replace O-rings at least once a year.

