



Internal view




Internal view




Internal view




Internal view



Internal view



Internal view



Motor view




Internal view




Remark: According to the statement of the manufacturer, the Anion Generator is not working during test and will not appear in the products for sale.


PCB view




PCB view




PCB view




PCB view




Internal view



Internal view




Internal view




Internal view



Internal view




Internal view




Internal view of adapter




Internal view of adapter




Internal view of adapter




Internal view of adapter



Internal view of adapter



Internal view of adapter



PCB view of adapter

