

Page 6 / 14

Report No.: T200610N03 Rev. 00

Internal Photo (Model: RMX-44 BT)







Page 7 / 14


Report No.: T200610N03 Rev. 00









Page 8 / 14 **Report No.:** T200610N03 Rev. 00









Page 9 / 14 **Report No.:** T200610N03 Rev. 00








Page 10 / 14 **Report No.:** T200610N03 Rev. 00








Page 11 / 14

Report No.: T200610N03 Rev. 00









Page 12 / 14

Report No.: T200610N03 Rev. 00









Page 13 / 14

Report No.: T200610N03 Rev. 00







Page 14 / 14 Report No.: T200610N03 Rev. 00

