






Date: 18 JAN 2025 15:00:01

### 11AX40SISO\_Ant1\_5230




Date: 18 JAN 2025 15:04:55

### 11AX40SISO\_Ant1\_5270




Date: 18 JAN 2025 15:06:24

11AX40SISO\_Ant1\_5310




Date: 18 JAN 2025 15:07:57

11AX40SISO\_Ant1\_5510




Date: 18 JAN 2025 15:11:38

11AX40SISO\_Ant1\_5550




Date: 18 JAN 2025 15:13:17

### 11AX40SISO\_Ant1\_5670




Date: 18 JAN 2025 15:15:34

### 11AX40SISO\_Ant1\_5710




Date: 17 FEB 2025 16:09:27

11A\_Ant1\_5745




Date: 18 JAN 2025 17:43:30

11A\_Ant1\_5785




Date: 18 JAN 2025 17:40:53

11A\_Ant1\_5825




Date: 18 JAN 2025 17:41:03

### 11N20SISO\_Ant1\_5745




Date: 18 JAN 2025 12:15:23

### 11N20SISO\_Ant1\_5785




Date: 18 JAN 2025 12:19:25

11N20SISO\_Ant1\_5825




Date: 18 JAN 2025 12:24:01

11N40SISO\_Ant1\_5755




Date: 18 JAN 2025 13:53:40

11N40SISO\_Ant1\_5795




Date: 18 JAN 2025 13:55:21

### 11AC20SISO\_Ant1\_5745




Date: 18 JAN 2025 14:11:50

### 11AC20SISO\_Ant1\_5785




Date: 18 JAN 2025 14:13:20

11AC20SISO\_Ant1\_5825



Date: 18 JAN 2025 14:13:20


11AC40SISO\_Ant1\_5755



Date: 18 JAN 2025 14:27:10


11AC40SISO\_Ant1\_5795






Date: 18 JAN 2025 14:28:49

### 11AX20SISO\_Ant1\_5745




Date: 18 JAN 2025 14:48:03

### 11AX20SISO\_Ant1\_5785




Date: 18 JAN 2025 14:52:27

11AX20SISO\_Ant1\_5825



Date: 20 FEB. 2025 10:35:24

11AX40SISO\_Ant1\_5755



Date: 18 JAN. 2025 15:17:18

11AX40SISO\_Ant1\_5795

