



10MHz_High_QPSK_1@49




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:17:54

10MHz_High_QPSK_50@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:18:52

10MHz_High_16QAM_1@49




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:19:51

10MHz_High_16QAM_50@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:21:48

15MHz_Low_QPSK_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:23:12

15MHz_Low_QPSK_75@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:24:25

15MHz_Low_16QAM_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:25:38

15MHz_Low_16QAM_75@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:26:50

15MHz_High_QPSK_1@74




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:28:07

15MHz_High_QPSK_75@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:29:19

15MHz_High_16QAM_1@74




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:30:30

15MHz_High_16QAM_75@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:31:42

20MHz_Low_QPSK_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:33:15

20MHz_Low_QPSK_100@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:34:38

20MHz_Low_16QAM_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:36:00

20MHz_Low_16QAM_100@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:37:23

20MHz_High_QPSK_1@99




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:38:54

20MHz_High_QPSK_100@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:40:17

20MHz_High_16QAM_1@99



ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:41:39

20MHz_High_16QAM_100@0



ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:43:02


Spurious Emissions at Antenna Terminal

FCC Part 22H & IC RSS 132

B5, Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 14.DEC.2024 09:42:55

1.4MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:51:15

1.4MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:51:34

3MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:51:57

3MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:52:16

3MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:52:35

5MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:53:00

5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:53:20

5MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:53:40

10MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:54:06

10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)



ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:54:26


10MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:54:47

FCC Part 24E & IC RSS 133

B2, Normal
1RB was the worst case




5MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:49:43

5MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:50:02

5MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:50:20

10MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:50:45

10MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:51:04

10MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:51:24

15MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:51:48

15MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:52:08

15MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:52:28

20MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:52:52

20MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:53:13







20MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:53:33

FCC Part 27 & IC RSS 139

B4, Normal
1RB was the worst case




5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:56:21

5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:56:40

5MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:57:00

10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:57:25

10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:57:45


10MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:58:04




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:58:26




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:58:45




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:59:04



ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:59:27



ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 08:59:46




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 09:00:05


FCC Part 27 & IC RSS 130

B12, Normal
1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~8.16GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




1.4MHz_High_QPSK_1@0(30MHz~8.16GHz)




3MHz_Low_QPSK_1@0(30MHz~8.16GHz)




3MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



3MHz_High_QPSK_1@0(30MHz~8.16GHz)




5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:57:31

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:57:51

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:58:11

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:58:35

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 14.DEC.2024 09:43:31

10MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:59:03

FCC Part 27 & IC RSS 130


B17, Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 10:47:03

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 10:47:36

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 10:48:10

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 10:48:51

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 10:49:26

10MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 10:50:01


FCC Part 27 & IC RSS 139

B66, Normal
1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



3MHz_High_QPSK_1@0(30MHz~18.8GHz)




5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 09:07:44

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 09:08:04

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 09:08:23

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 09:08:47

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 09:09:07

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 09:09:27

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 09:09:50

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 09:10:10

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 09:10:30

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 09:10:54

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 09:11:15

20MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 09:11:34


FCC Part 27 & IC RSS 199

B7, Normal
1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




5MHz_High_QPSK_1@0(30MHz~26.7GHz)




10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



10MHz_High_QPSK_1@0(30MHz~26.7GHz)




15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 09:03:06

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 09:03:28

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 09:03:49

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 09:04:17

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 09:04:39

20MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 13.DEC.2024 09:05:00


FCC Part 27 & IC RSS 199

B41, Normal
1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~27.55GHz)




5MHz_Middle_QPSK_1@0(30MHz~27.55GHz)




5MHz_High_QPSK_1@0(30MHz~27.55GHz)




10MHz_Low_QPSK_1@0(30MHz~27.55GHz)




10MHz_Middle_QPSK_1@0(30MHz~27.55GHz)



10MHz_High_QPSK_1@0(30MHz~27.55GHz)




15MHz_Low_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 14.DEC.2024 18:02:26

15MHz_Middle_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 14.DEC.2024 18:02:47

15MHz_High_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 14.DEC.2024 18:03:07

20MHz_Low_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 14.DEC.2024 18:03:30

20MHz_Middle_QPSK_1@0(30MHz~27.55GHz)



ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 14.DEC.2024 18:03:51

20MHz_High_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 14.DEC.2024 18:04:12


FCC Part 27N & IC RSS 130

B71, Normal
1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~7.98GHz)




5MHz_Middle_QPSK_1@0(30MHz~7.98GHz)




5MHz_High_QPSK_1@0(30MHz~7.98GHz)




10MHz_Low_QPSK_1@0(30MHz~7.98GHz)




10MHz_Middle_QPSK_1@0(30MHz~7.98GHz)



10MHz_High_QPSK_1@0(30MHz~7.98GHz)




15MHz_Low_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 11:03:42

15MHz_Middle_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 11:04:19

15MHz_High_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 11:04:53

20MHz_Low_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 11:05:34

20MHz_Middle_QPSK_1@0(30MHz~7.98GHz)



ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 11:06:12

20MHz_High_QPSK_1@0(30MHz~7.98GHz)



ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 15:47:26

==== END OF REPORT =====