

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2AT6B-0001
19-0320
August 22, 2019
Cort Business Services dba Tapdn
TAPDN-PIR-0001

Test Configuration Setup Photos



Figure 1. Radiated Emissions Test Setup

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2AT6B-0001
19-0320
August 22, 2019
Cort Business Services dba Tapdn
TAPDN-PIR-0001




Figure 2. Radiated Emissions, 9 kHz – 30 MHz

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2AT6B-0001
19-0320
August 22, 2019
Cort Business Services dba Tapdn
TAPDN-PIR-0001



Figure 3. Radiated Emissions, 30 MHz - 200 MHz

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2AT6B-0001
19-0320
August 22, 2019
Cort Business Services dba Tapdn
TAPDN-PIR-0001





Figure 4. Radiated Emissions, 200 MHz - 1000 MHz

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2AT6B-0001
19-0320
August 22, 2019
Cort Business Services dba Tapdn
TAPDN-PIR-0001



**Figure 5. Radiated Emissions, Above 1000 MHz
(unintentional emissions)**

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:


FCC Part 15.209/249
2AT6B-0001
19-0320
August 22, 2019
Cort Business Services dba Tapdn
TAPDN-PIR-0001



**Figure 6. Radiated Emissions Test Setup above 1 GHz
(intentional emissions)**

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2AT6B-0001
19-0320
August 22, 2019
Cort Business Services dba Tapdn
TAPDN-PIR-0001



**Figure 7. Radiated Emissions Test Setup above 1 GHz
(intentional emissions)**