

INTERTEK TESTING SERVICE

Report No: HK21120398

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Front View)
GS1005



INTERTEK TESTING SERVICE

Report No: HK21120398

Configuration Photographs

Worst-Case Line-Conducted Emissions

**(Rear View)
GS1005**



INTERTEK TESTING SERVICE

Report No: HK21120398

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Side View)
GS1005



INTERTEK TESTING SERVICE

Report No: HK21120398

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Front View)
GS1004



INTERTEK TESTING SERVICE

Report No: HK21120398

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Rear View)
GS1004



INTERTEK TESTING SERVICE

Report No: HK21120398

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Side View)
GS1004

