

Sutro Connect Inc.
181 2nd St.#21, San Francisco, CA 94105 United States

Class II Permissive Change Letter

FCC ID: **2ATKG-RAD78235**

Date: Oct. 26, 2021

To:
Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD

Subject: Request Class II Permissive Change for FCC ID: **2ATKG-RAD78235**

To Whom It May Concern,

The purpose of this letter is request a Class II Permissive Change for FCC ID: **2ATKG-RAD78235** original grant date: 10/22/2019;

Applicant: **Sutro Connect Inc.**

The main change filed under this application is the IC , Adapter and battery were changed, meet KDB 178919 D01: Hardware changes as follows;

Item	Description	Yes / No	Answer from applicant
1	Hardware changes	Yes	1. Some IC change and layout Modify to match new IC. Delete IC: MP1461/MP1462/MP2615/MP1605 Add IC: SY8263/SY6982/LP28400A/ 2. Adapter change from NT- 120300D1 to AS1201A- 0502000USU 3、 Battery change from LG to BAK.
2	There is no increase in the output power rating (unless such exceptions are permitted by rules or KDB publications – see V) G)).	Yes	Original power was 0.0789 W for RoLa, new power is 0.0719 W for RoLa.
3	The Equipment Class remains the same. (Changes that require a new Equipment Class code require a new grant of certification (FCC ID), except for SDR approvals.)	Yes	Same as original application; Equipment Class remains is DTS.
4	RF exposure changes must be addressed	Yes	Update revised RF exposure report;
5	There are no other changes to the device that indicate a need for a new FCC ID.	Yes	No any change.

Sutro Connect Inc.

181 2nd St.#21, San Francisco, CA 94105 United States

I attest that such change will affect the RF function out of the grant conditions, just need measured following items as follows;

Maximum Conducted Output Power

Radiated Spurious Emissions

Emissions at Restricted Band

AC Conducted Emissions

RF Exposure Evaluation

Should you have any questions or comments regarding this matter, please have my best attention.

Sincerely,

A handwritten signature in black ink, appearing to read 'Ravi Kurani', with a horizontal line extending from the bottom right.

(Signed)

Name / Title: Ravi Kurani / President

Company: Sutro Connect Inc.

Address: 181 2nd St.#21, San Francisco, CA 94105 United States

Phone: (951) 907-2532

Fax: /

E-Mail: eng@mysutro.com